

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### [(374942)] LIEBHERR TA230 137792-1513 - Front Axle

Sample No: LH0265836

Oil Type: NOT GIVEN



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0265836	---	---	---
Date d'échant.	22 Jun 2023	---	---	---
Heures de la Machine	1017	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	Changed	---	---	---
Statut de l'échant.	NORMAL	---	---	---

**PRIESTLY DEMOLITION INC**  
3200 LLOYDTOWN-AURORA RD.  
KING, ON  
CA L7B 0G3  
Contact: Service Manager



#### ÉTAT D'HUILE

Visc 40°C	cSt	● 63.8	---	---	---
-----------	-----	--------	-----	-----	-----

T:  
F:



#### CONTAMINATION

Silicium	ppm	● 15	---	---	---
Sodium	ppm	● 21	---	---	---
Potassium	ppm	● 2	---	---	---

#### Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 80 Tractor TDH Fluid. Please confirm the oil type and grade, and specify the brand of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



#### MÉTAUX D'USURE

Fer	ppm	● 149	---	---	---
Cuivre	ppm	● 81	---	---	---
Plomb	ppm	● 4	---	---	---
Étain	ppm	● 3	---	---	---
Aluminium	ppm	● 3	---	---	---
Chrome	ppm	● 2	---	---	---
Molybdène	ppm	● 0	---	---	---
Nickel	ppm	● 9	---	---	---
Titane	ppm	<1	---	---	---
Argent	ppm	0	---	---	---
Manganèse	ppm	5	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIFS

Calcium	ppm	● 3456	---	---	---
Magnésium	ppm	● 10	---	---	---
Zinc	ppm	● 1458	---	---	---
Phosphore	ppm	● 1248	---	---	---
Baryum	ppm	● 4	---	---	---
Bore	ppm	● 100	---	---	---

**Depot:** PRI320KIN  
**Unique No:** 5606856  
**Signed:** Kevin Marson  
**Report Date:** 14 Jul 2023



### GRAPHS

