

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 112349-1253 - Front Left Wheel Hub

Sample No: LH0274577

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0274577	LH0251436	LH0239551	LH0227664
Date d'échant.	30 Aug 2023	16 Jan 2023	25 Jul 2022	18 Mar 2022
Heures de la Machine	10003	8336	7203	6226
Heures de l'huile	0	0	0	0
Huile changée	Changed	Changed	Changed	Changed
Statut de l'échant.	NORMAL	NORMAL	NORMAL	NORMAL

MONAGHAN MUSHROOMS LTD
 7345 GUELPH LINE
 CAMPBELLVILLE, ON
 CA L0P 1B0
 Contact: Steven Cargill
 s.cargill@monaghan-mushrooms.com
 T:
 F:



ÉTAT D'HUILE

Visc 40°C	cSt	101	101	103	103



CONTAMINATION

Silicium	ppm	1	<1	<1	1
Sodium	ppm	2	1	2	<1
Potassium	ppm	<1	<1	<1	<1



MÉTAUX D'USURE

Fer	ppm	6	6	6	2
Cuivre	ppm	2	2	2	<1
Plomb	ppm	0	0	0	<1
Étain	ppm	0	0	0	0
Aluminium	ppm	<1	0	<1	0
Chrome	ppm	0	0	0	0
Molybdène	ppm	<1	0	0	<1
Nickel	ppm	0	<1	0	<1
Titane	ppm	0	0	0	0
Argent	ppm	0	0	0	2
Manganèse	ppm	0	0	0	<1
Vanadium	ppm	0	0	0	0



ADDITIFS

Calcium	ppm	21	23	28	8
Magnésium	ppm	2	1	2	2
Zinc	ppm	12	9	11	8
Phosphore	ppm	1305	1296	1229	1307
Baryum	ppm	<1	<1	<1	0
Bore	ppm	308	306	310	320

Diagnostic

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: MONCAM
 Unique No: 5632812
 Signed: Wes Davis
 Report Date: 31 Aug 2023



GRAPHS

