## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH60M 146313-1217 - Front Differential

Sample No: LH0274547
Oil Type: NOT GIVEN

_				
U INFO	RMATIC	ON SUR L'ÉCHA	NTILLON	
Numéro d'échant.		LH0274547	LH0247199	 
Date d'échant.		05 Sep 2023	14 Jun 2023	 
Heures de la Machine		1114	530	 
Heures de la Macrinie		0	0	 
Huile changée		N/A	Changed	 
Statut de l'echant.		NORMAL	NORMAL	 
Statut de rechant.		NORMAL	NONIVIAL	 
<b>ETAT</b>	<b>D'HUILE</b>			
Visc 40°C	cSt	<b>104</b>	O 146	 
-4				
CONT	AMINA	TION		
	AMINA			
Silicium	ppm	<b>3</b>	0 8	 
Sodium	ppm	<b>0</b> 1	O 4	 
Potassium	ppm	<b>()</b> <1	<b></b> <1	 
MéT/	AUX D'U	SURE		
Fer	ppm	<b>19</b>	O 13	 
Cuivre	ppm	0 17	O 19	 
Plomb	ppm	O <1	O <1	 
Étain	ppm	00	00	 
Aluminium	ppm	<b>○</b> <1	O <1	 
Chrome	ppm	00	00	 
Molybdène	ppm	0	0	 
Nickel	ppm	0	O <1	 
Titane	ppm	0	0	 
Argent	ppm	0	0	 
Manganèse	ppm	<1	<1	 
Vanadium	ppm	0	0	 
	ppiii	·	0	
ADDI	TIFS			
Calcium	ppm	11	6	 
Magnésium	ppm	1	<1	 
Zinc	ppm	16	15	 
Phosphore	ppm	1342	1691	 
Baryum	ppm	1	100	 

102



WENTWORTH METAL RECYCLING 495 WENTWORTH STREET NORTH HAMILTON, ON CA L8L 5X1 Contact: Jaason

jaason@wentworthrecycling.com

T: F:

#### Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 75W90 Gear Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:WENHAMUnique No:5633843Signed:Wes DavisReport Date:06 Sep 2023

307

ppm

Bore

# LIEBHERR







#### **GRAPHS**

