

LIEBHERR A904 056759-005 - Rear Left Wheel Hub

Sample No: LH

Oil Type: GEAR OIL SAE 80

INFORMATION SUR L'ÉCHANTILLON LH

0

N/A NORMAL

83.2

18 Oct 2023 14788

Numéro d'échant.	
Date d'échant.	
Heures de la Machine	
Heures de l'huile	
Huile changée	
Statut de l'echant.	

ÉTAT D'HUILE


Visc 40°C

cSt

21 C	
	CONT

	NTAMINA	TION		
Silicium	ppm	01	 	
Sodium	ppm	01	 	
Potassium	maa	0	 	

Ä				
₩ Mét/	LUX D'USL	IRE		
Fer	ppm	0 13	 	
Cuivre	ppm	04	 	
Plomb	ppm	○ <1	 	
Étain	ppm	0	 	
Aluminium	ppm	○ <1	 	
Chrome	ppm	0	 	
Molybdène	ppm	0	 	
Nickel	ppm	0	 	
Titane	ppm	0	 	
Argent	ppm	<1	 	
Manganèse	ppm	0	 	
Vanadium	ppm	0	 	





LIEBHERR CANADA LTEE

444 AVENUE DE LA FRICHE DOLBEAU-MISTASSINI, QC CA G8L 3M7 Contact: Luc Trottier luc.trottier@liebherr.com T: F: (418)276-9844

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80. Please confirm. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:	LBADOL
Unique No:	5668904
Signed:	Wes Davis
Report Date:	25 Oct 2023





GRAPHS

 $\overline{\mathbf{O}}$



ID du rapport: LBADOL [WCAMIS] 02591825 (Generated: 10/25/2023 15:33:34) Rev: 1

Submitted By: Olivier Galimi