



LIEBHERR A904 056759-005 - Rear Right Wheel Hub

Sample No: LH

Oil Type: GEAR OIL SAE 80

INFORMATION SUR L'ÉCHANTILLON

0

N/A NORMAL

82.9

18 Oct 2023 14788

Numéro d'échant.	
Date d'échant.	
Heures de la Machine	
Heures de l'huile	
Huile changée	
Statut de l'echant.	

ÉTAT D'HUILE

Visc 40°C

.....

cSt

CON1	AMINATIO	DN		
Silicium	ppm	01	 	
Sodium	ppm	02	 	
Potassium	ppm	0	 	

M				
Mé1	ΓΑυχ Ρυ	ISURE		
Fer	ppm	0 13	 	
Cuivre	ppm	04	 	
Plomb	ppm	0	 	
Étain	ppm	0 (
Aluminium	ppm	◯ <1	 	
Chrome	ppm	0 (
Molybdène	ppm	0 🔘	 	
Nickel	ppm	0 (
Titane	ppm	0	 	
Argent	ppm	<1	 	
Manganèse	ppm	0 (
Vanadium	ppm	0	 	

٥ **ADDITIFS** Calcium 0 139 ppm Magnésium 03 ppm Zinc ppm 0 116 0 1225 Phosphore ppm Baryum ppm ◯ <1 Bore 0 195 ppm



LIEBHERR CANADA LTEE

444 AVENUE DE LA FRICHE DOLBEAU-MISTASSINI, QC CA G8L 3M7 Contact: Luc Trottier luc.trottier@liebherr.com T: F: (418)276-9844

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80. Please confirm. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:	LBADOL
Unique No:	5668908
Signed:	Wes Davis
Report Date:	25 Oct 2023





GRAPHS

 \odot



ID du rapport: LBADOL [WCAMIS] 02591829 (Generated: 10/25/2023 15:33:42) Rev: 1

Submitted By: Olivier Galimi