

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR A910 141693-1837 - Rear Left Wheel Hub

Sample No: LH0249757

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90



JOSH LASALLE CONSTRUCTION EQUIPMENT LTD  
541 PIONEER RD.  
MERRICKVILLE, ON  
CA K0G 1N0  
Contact: Service Manager



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0249757	LH0249735	---	---
Date d'échant.	02 Nov 2023	26 Jun 2023	---	---
Heures de la Machine	1104	501	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---



#### ÉTAT D'HUILE

Visc 40°C	cSt	90.6	80.3	---	---
-----------	-----	------	------	-----	-----



#### CONTAMINATION

Silicium	ppm	7	10	---	---
Sodium	ppm	4	5	---	---
Potassium	ppm	2	4	---	---



#### MÉTAUX D'USURE

Fer	ppm	63	64	---	---
Cuivre	ppm	15	9	---	---
Plomb	ppm	<1	<1	---	---
Étain	ppm	0	0	---	---
Aluminium	ppm	<1	2	---	---
Chrome	ppm	<1	<1	---	---
Molybdène	ppm	0	<1	---	---
Nickel	ppm	<1	<1	---	---
Titane	ppm	<1	2	---	---
Argent	ppm	<1	4	---	---
Manganèse	ppm	<1	1	---	---
Vanadium	ppm	0	0	---	---



#### ADDITIFS

Calcium	ppm	537	830	---	---
Magnésium	ppm	3	4	---	---
Zinc	ppm	983	1514	---	---
Phosphore	ppm	1001	750	---	---
Baryum	ppm	3	5	---	---
Bore	ppm	193	110	---	---

T:  
F:

#### Diagnostic

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: JOSMER  
Unique No: 5671058  
Signed: Kevin Marson  
Report Date: 03 Nov 2023



### GRAPHS

