

LIEBHERR

CONSTRUCTION EQUIPMENT



[(353863)] **LIEBHERR L586 061826-1761 - Front Left Wheel Hu**

Sample No: LH0192734

Oil Type: SHELL SPIRAX HD 80W90



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0192734	LH0195349	LH0195344	LH0209022
Date d'échant.	02 Nov 2023	14 Jun 2023	19 Apr 2023	19 Dec 2022
Heures de la Machine	2913	17003	15800	13487
Heures de l'huile	0	0	0	2890
Huile changée	Changed	Changed	Changed	Changed
Statut de l'échant.	NORMAL	NORMAL	NORMAL	NORMAL

AV Terrace Bay Inc.

21 Mill Rd.

Terrace Bay, ON

CA P0T 2W0

Contact: Naqshe Iqbal

naqshe.iqbal@adityabirla.com

T: (807)823-0761

F:



ÉTAT D'HUILE

Visc 40°C	cSt	138	140	164	138
-----------	-----	-----	-----	-----	-----



CONTAMINATION

Silicium	ppm	1	1	1	2
Sodium	ppm	<1	<1	1	2
Potassium	ppm	0	<1	<1	<1



MÉTAUX D'USURE

Fer	ppm	57	24	19	112
Cuivre	ppm	12	7	6	16
Plomb	ppm	<1	0	<1	<1
Étain	ppm	0	<1	<1	1
Aluminium	ppm	<1	<1	<1	<1
Chrome	ppm	0	<1	<1	<1
Molybdène	ppm	0	<1	0	0
Nickel	ppm	<1	<1	<1	<1
Titane	ppm	0	0	0	0
Argent	ppm	<1	0	0	0
Manganèse	ppm	<1	<1	1	9
Vanadium	ppm	0	0	0	0



ADDITIFS

Calcium	ppm	15	12	12	0
Magnésium	ppm	0	<1	<1	1
Zinc	ppm	11	8	10	10
Phosphore	ppm	720	898	1978	763
Baryum	ppm	<1	0	0	0
Bore	ppm	2	3	12	2

Diagnostic

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: AVTTER

Unique No: 5672484

Signed: Wes Davis

Report Date: 09 Nov 2023



GRAPHS

