

[(365443)] LIEBHERR R966 054115-1783 - Diesel Engine

Sample No: LH0277606

Oil Type: DIESEL ENGINE OIL SAE 10W30

INFORMATION SUR L'ÉCHANTILLON

0 11.3

54

Numéro d'échant.	LH0277606	 	
Date d'échant.	29 Nov 2023	 	
Heures de la Machine	0	 	
Heures de l'huile	0	 	
Huile changée	Not Changd	 	
Statut de l'echant.	NORMAL	 	

Visc 100°C cSt Oxvdation (PA) %

Oxydation (PA)

Eau	%	NEG				
% de suie	%	0				
Nitration (PA)	%	39				
Sulfatation (PA)	%	50				
Glycol	%	NEG				
Essence	%	0.6				
Silicium	ppm	04				
Sodium	ppm	01				
Potassium	ppm	○ <1				

MéTAUX D'USURE

Fer	ppm	3				
Cuivre	ppm	0 22				
Plomb	ppm	01				
Étain	ppm	0 0				
Aluminium	ppm	01				
Chrome	ppm	0 0				
Molybdène	ppm	58				
Nickel	ppm	○ <1				
Titane	ppm	0 🔘				
Argent	ppm	○ <1				
Manganèse	ppm	0 🔘				
Vanadium	ppm	0				

0 **ADDITIFS** Calcium 0 1044 ppm Magnésium 0 971 ppm Zinc 0 1177 ppm Phosphore 0 1008 ppm Baryum ppm ◯ <1 Bore 01 ppm



CON-DRAIN LTD.

30 FLORAL PARKWAY CONCORD, ON CA L4K 4R1 Contact: B BAXTER B.BAXTER@CONDRAIN.COM T: F:

Diagnostic


No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.





GRAPHS

 \odot



ID du rapport: CON30CON [WCAMIS] 02600050 (Generated: 12/04/2023 13:13:45) Rev: 1