

LIEBHERR

CONSTRUCTION EQUIPMENT



[(374940)] LIEBHERR LH30M 137944-1253 - Transmission (M

Sample No: LH0278726

Oil Type: {unknown}



KINGS AUTO WRECKERS
1866 DRUMMOND LINE
PETERBOROUGH, ON
CA K9J 6X8
Contact: Service Manager

T:
F:



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0278726	LH0216025	---	---
Date d'échant.	22 Feb 2024	31 Aug 2022	---	---
Heures de la Machine	2777	551	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---



ÉTAT D'HUILE

Visc 40°C	cSt	53.8	52.0	---	---
-----------	-----	------	------	-----	-----



CONTAMINATION

Eau	%	NEG	NEG	---	---
Silicium	ppm	4	3	---	---
Sodium	ppm	23	40	---	---
Potassium	ppm	3	3	---	---



MÉTAUX D'USURE

Fer	ppm	22	11	---	---
Cuivre	ppm	22	16	---	---
Plomb	ppm	<1	<1	---	---
Étain	ppm	<1	<1	---	---
Aluminium	ppm	2	3	---	---
Chrome	ppm	0	0	---	---
Molybdène	ppm	31	0	---	---
Nickel	ppm	0	0	---	---
Titane	ppm	0	<1	---	---
Argent	ppm	0	<1	---	---
Manganèse	ppm	9	9	---	---
Vanadium	ppm	0	<1	---	---



ADDITIFS

Calcium	ppm	2112	3187	---	---
Magnésium	ppm	507	10	---	---
Zinc	ppm	1156	1066	---	---
Phosphore	ppm	1088	1070	---	---
Baryum	ppm	<1	<1	---	---
Bore	ppm	4	6	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: KINPET
Unique No: 5734806
Signed: Kevin Marson
Report Date: 23 Feb 2024



GRAPHS

