## **CONSTRUCTION EQUIPMENT**

### LIEBHERR L586 059953-1334 - Rear Right Wheel Hub

Sample No: LH0270302

**Oil Type:** PETRO CANADA TRAXON 75W90 SYNTHETIC

0 95.1

	538			
0		EL "		- AND
			-	

THOMAS CAVANAGH CONSTRUCTION LTD RR # 2, 9094 CAVANAGH ROAD ASHTON, ON CA K0A 1B0

Contact: Keith

T: (613)257-4995 F: (613)253-0071

### Diagnostic

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

INFORMATION SUR L'ÉCHANTILLON						
Numéro d'échant.	LH0270302					
Date d'échant.	05 Mar 2024					
Heures de la Machine	7962					
Heures de l'huile	0					
Huile changée	Changed					
Statut de l'echant.	NORMAL					

ÉTAT D'HUILE

Visc 40	°C
- <b>1</b>	

......

# cSt

	NTAMIN/	TION		
Eau	%	NEG	 	
Silicium	ppm	8 🔘	 	
Sodium	ppm	0 2	 	
Potassium	ppm	<b>○</b> <1	 	

🥰 Mét	'AUX D'L	JSURE		
Fer	ppm	0 49	 	
Cuivre	ppm	0 27	 	
Plomb	ppm	<b>○</b> <1	 	
Étain	ppm	01	 	
Aluminium	ppm	<b>○</b> <1	 	
Chrome	ppm	<mark></mark> <1	 	
Molybdène	ppm	0	 	
Nickel	ppm	<b>○</b> <1	 	
Titane	ppm	0	 	
Argent	ppm	<1	 	
Manganèse	ppm	01	 	
Vanadium	ppm	0	 	

ø **ADDITIFS** Calcium 269 ppm 04 Magnésium ppm Zinc 191 ppm Phosphore 2652 ppm Baryum 0 ppm Bore ppm 34

> Depot: Unique No: Signed: **Report Date:**

#### CAVASH 5737780 Kevin Marson 08 Mar 2024

Submitted By: ?





GRAPHS

 $\overline{\mathbf{O}}$ 

