

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR A914 128834-1507 - Front Left Wheel Hub

Sample No: LH0261829

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90



1000360735 ONTARIO LTD  
4848 CALABOGIE ROAD  
CALABOGIE, ON  
CA K0J 1H0  
Contact: Service Manager



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0261829	---	---	---
Date d'échant.	08 Mar 2024	---	---	---
Heures de la Machine	2498	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	Changed	---	---	---
Statut de l'échant.	NORMAL	---	---	---



#### ÉTAT D'HUILE

Visc 40°C	cSt	● 145	---	---	---
-----------	-----	-------	-----	-----	-----



#### CONTAMINATION

Eau	%	NEG	---	---	---
Silicium	ppm	● 4	---	---	---
Sodium	ppm	● 7	---	---	---
Potassium	ppm	● <1	---	---	---



#### MÉTAUX D'USURE

Fer	ppm	● 160	---	---	---
Cuivre	ppm	● 10	---	---	---
Plomb	ppm	● <1	---	---	---
Étain	ppm	● <1	---	---	---
Aluminium	ppm	● 2	---	---	---
Chrome	ppm	● 1	---	---	---
Molybdène	ppm	● 0	---	---	---
Nickel	ppm	● <1	---	---	---
Titane	ppm	● 0	---	---	---
Argent	ppm	0	---	---	---
Manganèse	ppm	● 1	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIFS

Calcium	ppm	267	---	---	---
Magnésium	ppm	● 5	---	---	---
Zinc	ppm	● 76	---	---	---
Phosphore	ppm	1901	---	---	---
Baryum	ppm	● 6	---	---	---
Bore	ppm	33	---	---	---

T:  
F:

#### Diagnostic

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: 100CAL  
Unique No: 5746322  
Signed: Kevin Marson  
Report Date: 11 Mar 2024



### GRAPHS

