# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### [ELG] LIEBHERR A924C 036737-1049 - Rear Right Wheel Hub

Sample No: LH

Oil Type: GEAR OIL SAE 80

<b>5</b>						
INFORMATION SUR L'ÉCHANTILLON						
Numéro d'échant.	LH					
Date d'échant.	14 Mar 2024					
Heures de la Machine	17745					
Heures de l'huile	0					
Huile changée	N/A					
Statut de l'echant.	NORMAL					
<b>A</b>						

<b>A</b>	
1	
/isc 40°	
/isc 40°	

CONTAMINATION							
Eau	%	NEG					
Silicium	ppm	<b>1</b>					
Sodium	ppm	<b>2</b>					
Potassium	ppm	<b>2</b>					

(O) MÁ				
Mé1	TAUX D'U	ISURE		
Fer	ppm	<b>41</b>	 	
Cuivre	ppm	<b>3</b>	 	
Plomb	ppm	<b>0</b> 0	 	
Étain	ppm	<b>0</b>	 	
Aluminium	ppm	<b>()</b> <1	 	
Chrome	ppm	<b>0</b>	 	
Molybdène	ppm	<b>0</b>	 	
Nickel	ppm	<b>○</b> <1	 	
Titane	ppm	<b>0</b>	 	
Argent	ppm	<1	 	
Manganèse	ppm	<b>0</b>	 	
Vanadium	ppm	0	 	

ADDITIFS						
Calcium	ppm	<b>22</b>				
Magnésium	ppm	<b>○</b> <1				
Zinc	ppm	<b>10</b>				
Phosphore	ppm	<b>1247</b>				
Baryum	ppm	<b>0</b>				
Bore	ppm	<b>307</b>				



ELG Canada 4375 CORPORATE DRIVE BURLINGTON, ON CA L7L 5P7 Contact: Service Manager

T:

F: (905)335-9687

#### Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80. Please confirm. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:STR437BURUnique No:5747572Signed:Wes DavisReport Date:15 Mar 2024

# LIEBHERR

CONSTRUCTION EQUIPMENT





### **GRAPHS**

