

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR 151293-1216 - Transmission (Manual)

Sample No: LH0290915

Oil Type: TDTO FLUID SAE 10W



1625066 ONTARIO LTD.  
870 MACKAY RD  
PICKERING, ON  
CA L1W 2Y4  
Contact: Service Manager



#### Information sur l'échantillon

Numéro d'échant.	LH0290915	---	---	---
Date d'échant.	21 May 2024	---	---	---
Heures de la Machine	1496	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	Changed	---	---	---
Statut de l'échant.	NORMAL	---	---	---



#### État d'huile

Visc 40°C	cSt	● 43.8	---	---	---
-----------	-----	--------	-----	-----	-----



#### Contamination

Eau	%	NEG	---	---	---
Silicium	ppm	● 2	---	---	---
Sodium	ppm	● 46	---	---	---
Potassium	ppm	● 4	---	---	---



#### Métaux d'usure

Fer	ppm	● 23	---	---	---
Cuivre	ppm	● 31	---	---	---
Plomb	ppm	● <1	---	---	---
Étain	ppm	● <1	---	---	---
Aluminium	ppm	● 4	---	---	---
Chrome	ppm	● <1	---	---	---
Molybdène	ppm	● 0	---	---	---
Nickel	ppm	● <1	---	---	---
Titane	ppm	● 0	---	---	---
Argent	ppm	● 0	---	---	---
Manganèse	ppm	● 47	---	---	---
Vanadium	ppm	● 0	---	---	---



#### Additifs

Calcium	ppm	● 3227	---	---	---
Magnésium	ppm	● 8	---	---	---
Zinc	ppm	● 1135	---	---	---
Phosphore	ppm	● 1078	---	---	---
Baryum	ppm	● 2	---	---	---
Bore	ppm	● 4	---	---	---

T:  
F:

#### Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDTO FLUID SAE 10W. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: 162PIC  
Unique No: 5786151  
Signed: Wes Davis  
Report Date: 22 May 2024



### Graphs

