

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### [(362420)] LIEBHERR L580 065390-17 60 - Transmission (Ma

Sample No: LH

Oil Type: DTRAN SYP 20



#### Information sur l'échantillon

Numéro d'échant.	LH	LH0218121	---	---
Date d'échant.	14 May 2024	13 Feb 2023	---	---
Heures de la Machine	11819	700	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---

HUBERT & FILS

474 ROUTE 105  
BOIS-FRANC, QC  
CA J9E 3A9

Contact: Eric Brisebois

ericbrisebois99@gmail.com

T:

F:



#### État d'huile

Visc 40°C	cSt	39.1	41.7	---	---
-----------	-----	------	------	-----	-----



#### Contamination

Eau	%	NEG	NEG	---	---
Silicium	ppm	7	7	---	---
Sodium	ppm	<1	19	---	---
Potassium	ppm	<1	2	---	---



#### Métaux d'usure

Fer	ppm	8	11	---	---
Cuivre	ppm	<1	2	---	---
Plomb	ppm	0	<1	---	---
Étain	ppm	0	0	---	---
Aluminium	ppm	1	1	---	---
Chrome	ppm	0	0	---	---
Molybdène	ppm	0	0	---	---
Nickel	ppm	0	<1	---	---
Titane	ppm	0	<1	---	---
Argent	ppm	0	0	---	---
Manganèse	ppm	0	<1	---	---
Vanadium	ppm	0	0	---	---



#### Additifs

Calcium	ppm	3809	3618	---	---
Magnésium	ppm	15	8	---	---
Zinc	ppm	1451	1388	---	---
Phosphore	ppm	1212	1234	---	---
Baryum	ppm	0	0	---	---
Bore	ppm	109	99	---	---

#### Diagnostic

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: HUBBOI

Unique No: 5787699

Signed: Wes Davis

Report Date: 30 May 2024



### Graphs

