

LIEBHERR TA 230 150775-1513 - Hydraulic System

Sample No: LH0289913 {unknown}

Oil Type:

Information sur l'échantillon

0 46.7

Numéro d'échant.	LH0289913	 	
Date d'échant.	17 May 2024	 	
Heures de la Machine	1196	 	
Heures de l'huile	0	 	
Huile changée	Not Changd	 	
Statut de l'echant	NORMAL	 	

État d'huile

Visc 40°C

cSt

Contamination					
Eau	%	NEG			
Particules >4µ		0 15323			
Particules >6µ		604			
Particules >14µ		0 32			
ISO 4406:1999 (c)		21/16/12			
Silicium	ppm	3			
Sodium	ppm	01			
Potassium	ppm	01			

Métaux d'usure

Calcium	ppm	1385				
Magnésium	ppm	5				
Zinc	ppm	683				
Phosphore	ppm	612				
Baryum	ppm	<1				
Bore	ppm	<1				





LES ENTREPRISES LOU-VIL INC 255 BOUL. LOUIS XIV QUEBEC, QC CA G2K 1W6 Contact: Service Manager

T: (418)622-2958 F:

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: **Report Date:** LOUQUE 5788821 Wes Davis 05 Jun 2024 Submitted By: ?

LEBHERR CONSTRUCTION EQUIPMENT



All:-----

Graphs

Ö

