

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH22M 158368-1250 - Rear Right Wheel Hub

Sample No: LH0284692

Oil Type: SAE 75W90



BELLEMARE RECYCLAGE - SABLE DES FORGES INC
8750 BOUL INDUSTRIEL
TROIS-RIVIERES, QC
CA G9A 5E1
Contact: Sacha Bellemare
sachabellemare@groupebellemare.com
T: (819)296-3767
F: (819)296-1116



Information sur l'échantillon

Numéro d'échant.	LH0284692	LH0284725	---	---
Date d'échant.	25 Jun 2024	10 Apr 2024	---	---
Heures de la Machine	1070	500	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	N/A	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---



État d'huile

Visc 40°C	cSt	90.4	65.0	---	---
-----------	-----	------	------	-----	-----



Contamination

Eau	%	NEG	NEG	---	---
Silicium	ppm	1	5	---	---
Sodium	ppm	4	15	---	---
Potassium	ppm	<1	<1	---	---



Métaux d'usure

Fer	ppm	7	15	---	---
Cuivre	ppm	2	4	---	---
Plomb	ppm	0	0	---	---
Étain	ppm	0	0	---	---
Aluminium	ppm	<1	<1	---	---
Chrome	ppm	0	0	---	---
Molybdène	ppm	0	0	---	---
Nickel	ppm	<1	0	---	---
Titane	ppm	0	0	---	---
Argent	ppm	<1	0	---	---
Manganèse	ppm	<1	5	---	---
Vanadium	ppm	0	0	---	---



Additifs

Calcium	ppm	646	3499	---	---
Magnésium	ppm	4	10	---	---
Zinc	ppm	288	1406	---	---
Phosphore	ppm	1154	1138	---	---
Baryum	ppm	<1	1	---	---
Bore	ppm	237	104	---	---

Diagnostic

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: GESTRO
Unique No: 5802223
Signed: Wes Davis
Report Date: 28 Jun 2024



Graphs

