

LIEBHERR

CONSTRUCTION EQUIPMENT



[(375485)] LIEBHERR L556 068166-1826 - Front Left Wheel H

Sample No: LH0296381

Oil Type: {unknown}



Information sur l'échantillon

Numéro d'échant.	LH0296381	---	---	---
Date d'échant.	07 Jul 2024	---	---	---
Heures de la Machine	3403	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	Changed	---	---	---
Statut de l'échant.	NORMAL	---	---	---

MILLER WASTE SYSTEMS

8050 WOODBINE AVE

MARKHAM, ON

CA L3R 2N8

Contact: Gord Allan



État d'huile

Visc 40°C	cSt	83.8	---	---	---
-----------	-----	------	-----	-----	-----

T:

F: (905)475-6396



Contamination

Eau	%	NEG	---	---	---
Silicium	ppm	5	---	---	---
Sodium	ppm	2	---	---	---
Potassium	ppm	<1	---	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



Métaux d'usure

Fer	ppm	77	---	---	---
Cuivre	ppm	17	---	---	---
Plomb	ppm	0	---	---	---
Étain	ppm	1	---	---	---
Aluminium	ppm	<1	---	---	---
Chrome	ppm	<1	---	---	---
Molybdène	ppm	0	---	---	---
Nickel	ppm	<1	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	0	---	---	---
Manganèse	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



Additifs

Calcium	ppm	10	---	---	---
Magnésium	ppm	2	---	---	---
Zinc	ppm	47	---	---	---
Phosphore	ppm	2588	---	---	---
Baryum	ppm	<1	---	---	---
Bore	ppm	88	---	---	---

Depot: MILMAR

Unique No: 5812016

Signed: Kevin Marson

Report Date: 09 Jul 2024



Graphs

