

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR TA230 142551-1513 - Transmission (Auto)

Sample No: LH0292112

Oil Type: DEXRON III



LES ENTREPRISES LOU-VIL INC
255 BOUL. LOUIS XIV
QUEBEC, QC
CA G2K 1W6
Contact: Service Manager

T: (418)622-2958
F:



Information sur l'échantillon

Numéro d'échant.	LH0292112	---	---	---
Date d'échant.	28 Jun 2024	---	---	---
Heures de la Machine	2065	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	Not Chngd	---	---	---
Statut de l'échant.	NORMAL	---	---	---



État d'huile

Visc 40°C	cSt	● 34.7	---	---	---
-----------	-----	--------	-----	-----	-----



Contamination

Eau	%	NEG	---	---	---
Silicium	ppm	● 4	---	---	---
Sodium	ppm	● 3	---	---	---
Potassium	ppm	● 1	---	---	---



Métaux d'usure

Fer	ppm	● 68	---	---	---
Cuivre	ppm	● 8	---	---	---
Plomb	ppm	● 0	---	---	---
Étain	ppm	● 0	---	---	---
Aluminium	ppm	● 2	---	---	---
Chrome	ppm	● 0	---	---	---
Molybdène	ppm	● 0	---	---	---
Nickel	ppm	● <1	---	---	---
Titane	ppm	● 0	---	---	---
Argent	ppm	● 0	---	---	---
Manganèse	ppm	● <1	---	---	---
Vanadium	ppm	● 0	---	---	---



Additifs

Calcium	ppm	● 152	---	---	---
Magnésium	ppm	● 2	---	---	---
Zinc	ppm	● 14	---	---	---
Phosphore	ppm	● 273	---	---	---
Baryum	ppm	● 2	---	---	---
Bore	ppm	● 115	---	---	---

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: LOUQUE
Unique No: 5812632
Signed: Wes Davis
Report Date: 10 Jul 2024



Graphs

