

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### [(366972)] LIEBHERR LH50M 134369-1216 - Rear Left Wheel

Sample No: LH0223785

Oil Type: LIEBHERR GEAR BASIC 90 LS



9192-2443 QUEBEC INC. EQUIPEMENT REBP  
175 PORTAGE DES MOUSSES  
PORT CARTIER, QC  
CA G5B 2V9  
Contact: Service Manager



#### Information sur l'échantillon

Numéro d'échant.	LH0223785	LH	LH0119148	---
Date d'échant.	14 Jul 2024	25 Mar 2023	14 Sep 2022	---
Heures de la Machine	0	1905	861	---
Heures de l'huile	0	0	0	---
Huile changée	N/A	N/A	Changed	---
Statut de l'échant.	NORMAL	NORMAL	NORMAL	---



#### État d'huile

Visc 40°C	cSt	176	186	141	---
-----------	-----	-----	-----	-----	-----



#### Contamination

Eau	%	NEG	NEG	NEG	---
Silicium	ppm	8	18	12	---
Sodium	ppm	5	6	2	---
Potassium	ppm	<1	<1	<1	---



#### Métaux d'usure

Fer	ppm	30	37	12	---
Cuivre	ppm	16	8	18	---
Plomb	ppm	<1	0	<1	---
Étain	ppm	0	0	0	---
Aluminium	ppm	1	2	<1	---
Chrome	ppm	0	0	0	---
Molybdène	ppm	0	1	6	---
Nickel	ppm	<1	<1	0	---
Titane	ppm	0	<1	0	---
Argent	ppm	0	0	0	---
Manganèse	ppm	1	1	<1	---
Vanadium	ppm	0	0	0	---



#### Additifs

Calcium	ppm	27	91	73	---
Magnésium	ppm	<1	<1	<1	---
Zinc	ppm	25	29	48	---
Phosphore	ppm	2239	2366	1299	---
Baryum	ppm	<1	0	0	---
Bore	ppm	2	3	5	---

T:  
F:

#### Diagnostic

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: 919POR  
Unique No: 5813447  
Signed: Kevin Marson  
Report Date: 16 Jul 2024



### Graphs

