

Machine Id  
**SEW EURODRIVE 24**

Component  
**Port Gearbox**  
Fluid

**DIAGNOSIS**

**Recommendation**

Resample at the next service interval to monitor.

**Wear**

All component wear rates are normal.

**Contamination**

There is no indication of any contamination in the component.

**Fluid Condition**



The condition of oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number	Client Info			<b>PC</b>	---	---
Sample Date	Client Info			<b>22 May 2002</b>	---	---
Machine Age	yrs	Client Info		<b>5</b>	---	---
Oil Age	yrs	Client Info		<b>9</b>	---	---
Oil Changed	Client Info			<b>N/A</b>	---	---
Sample Status				<b>NORMAL</b>	---	---





CONTAMINATION		method	limit/base	current	history1	history2
Water	WC Method			<b>NEG</b>	---	---

SAMPLE IMAGES		method	limit/base	current	history1	history2
Color					<i>no image</i>	<i>no image</i>
Bottom					<i>no image</i>	<i>no image</i>

# OIL ANALYSIS REPORT



## GRAPHS



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : PC  
**Lab Number** : 00949575  
**Unique Number** : 1239560  
**Test Package** : IND 2

**BUNGE CANADA (CAN-AMERA FOODS INC)**  
 2190 SOUTH SERVICE ROAD  
 OAKVILLE, ON  
 CA L6L 5N1  
 Contact: Dave Zeller  
 david.zeller@bunge.com  
 T: (905)825-7957  
 F: (905)825-7951

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.