


Machine Id
SEW EURODRIVE 25
Component
Port Gearbox
Fluid



DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.
Please note that this is a corrected copy.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the component.

Fluid Condition




The condition of oil is suitable for further service.
The viscosity index is 243.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number	Client Info			PC	---	---
Sample Date	Client Info			22 May 2002	---	---
Machine Age	yrs	Client Info		5	---	---
Oil Age	yrs	Client Info		9	---	---
Oil Changed	Client Info			N/A	---	---
Sample Status				NORMAL	---	---





CONTAMINATION		method	limit/base	current	history1	history2
Water	WC Method			NEG	---	---

SAMPLE IMAGES		method	limit/base	current	history1	history2
Color					<i>no image</i>	<i>no image</i>
Bottom					<i>no image</i>	<i>no image</i>

OIL ANALYSIS REPORT



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC
Lab Number : 00949577
Unique Number : 1239562
Test Package : IND 2

BUNGE CANADA (CAN-AMERICA FOODS INC)
 2190 SOUTH SERVICE ROAD
 OAKVILLE, ON
 CA L6L 5N1
 Contact: Dave Zeller
 david.zeller@bunge.com
 T: (905)825-7957
 F: (905)825-7951

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.