


OIL ANALYSIS REPORT



Haul Truck HT5023

Component **Front Right Wheel Hub**

PETRO CANADA TRAXON 85W140 (13 LTR)





DIAGNOSIS

Recommendation

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

Viscosity of sample indicates oil is within SAE 80W90 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The condition of the oil is acceptable for the time in service.

SAMPLE INFOR	MATION	method	limit/base	current	history 1	history 2
Sample Number		Client Info		PC0067293		
Sample Date		Client Info		04 Jun 2023		
Machine Age	hrs	Client Info		9532		
Oil Age	hrs	Client Info		0		
Oil Changed	1113	Client Info		N/A		
Sample Status		Ollerit IIIIO		ABNORMAL		
· ·				ABNORWAL		
WEAR METAL	S	method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185(m)	>500	60		
Chromium	ppm	ASTM D5185(m)	>8	<1		
Nickel	ppm	ASTM D5185(m)	>5	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>5	<1		
Lead	ppm	ASTM D5185(m)	>5	<1		
Copper	ppm	ASTM D5185(m)	>50	6		
Tin	ppm	ASTM D5185(m)		0		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185(m)	243	35		
Barium	ppm	ASTM D5185(m)	0	0		
Molybdenum	ppm	ASTM D5185(m)		<1		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)	0	8		
Calcium	ppm	ASTM D5185(m)	0	316		
Phosphorus	ppm	ASTM D5185(m)	988	594		
Zinc	ppm	ASTM D5185(m)	0	80		
Sulfur	ppm	ASTM D5185(m)	24530	18185		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	ITS	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185(m)	>25	3		
Sodium	ppm	ASTM D5185(m)	720	<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
VISUAL	le le · · ·	method	limit/base	current	history 1	history 2
White Metal	scalar	Visual*	NONE	VLITE		
Yellow Metal		Visual*	NONE	NONE		
	scalar	Visual*	NONE	NONE		
Precipitate	scalar		NONE	_		
Silt Debris	scalar	Visual* Visual*		NONE NONE		
	scalar		NONE			
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual* Visual*	>0.2	NEG NEG		
Free Water						



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: PC0067293

: 02567831 : 5604877

Received Diagnosed Diagnostician : Kevin Marson

: 04 Jul 2023

: 05 Jul 2023

Test Package : MOB 1 (Additional Tests: KV100, VI) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Lakeshore Gold Timmins West

Timmins, ON CA

Contact: Adam Koscielak adam.koscielak@HFSinclair.com

> T: F: