


OIL ANALYSIS REPORT



Scoop 6 Yard LHD6101

Component **Rear Differential**

PETRO CANADA TRAXON 80W90 (29 LTR)





DIAGNOSIS

Recommendation

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

XON 80W90 (29	LTR)			Apr2023		
SAMPLE INFOR	MATION	method	limit/base	current	history 1	history 2
Sample Number		Client Info		PC0048009		
Sample Date		Client Info		22 Apr 2023		
Machine Age	hrs	Client Info		5260		
Oil Age	hrs	Client Info		0		
Oil Changed	0	Client Info		N/A		
Sample Status				NORMAL		
WEAR METAL	_S	method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185(m)	>500	36		
Chromium	ppm	ASTM D5185(m)	>10	<1		
Nickel	ppm	ASTM D5185(m)	>10	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	<1		
Lead	ppm	ASTM D5185(m)	>25	0		
Copper	ppm	ASTM D5185(m)	>100	3		
Tin	ppm	ASTM D5185(m)	>10	0		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)	70	0		
Beryllium		ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
	ppm					
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185(m)	243	39		
Barium	ppm	ASTM D5185(m)	1	10		
Molybdenum	ppm	ASTM D5185(m)		<1		
Manganese	ppm	ASTM D5185(m)		1		
Magnesium	ppm	ASTM D5185(m)	2	3		
Calcium	ppm	ASTM D5185(m)	6	8		
Phosphorus	ppm	ASTM D5185(m)	987	698		
Zinc	ppm	ASTM D5185(m)	1	10		
Sulfur	ppm	ASTM D5185(m)	21530	21664		
_ithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	NTS	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185(m)	>75	2		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	VLITE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual*	>.2	NEG		
Free Water	scalar			NEG		
20.52) Pay: 1					Cubmitted E	Du Lua Dalanga



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: PC0048009

: 02567842 : 5604888

Received Diagnosed

: 04 Jul 2023 : 04 Jul 2023 Diagnostician : Wes Davis

Test Package : MOB 1 (Additional Tests: KV100, VI) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Lakeshore Gold Timmins West

Timmins, ON CA

Contact: Adam Koscielak adam.koscielak@HFSinclair.com

> T: F: