


# **OIL ANALYSIS REPORT**

EX0358

Component

Rear Left Drive

PETRO CANADA TRAXON E SYNTHETIC 80W-140 (--- GAL)



### **DIAGNOSIS**

### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the


### Fluid Condition

Viscosity of sample indicates oil is within SAE 90W140 range, advise investigate. The condition of the oil is acceptable for the time in service.

	` '			Jul2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL		
Sample Date		Client Info		28 Jul 2023		
Machine Age	hrs	Client Info		22000		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>500	256		
Chromium	ppm	ASTM D5185(m)	>10	3		
Nickel	ppm	ASTM D5185(m)	>5	<1		
Titanium	ppm	ASTM D5185(m)		<1		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>10	18		
Lead	ppm	ASTM D5185(m)	>10	0		
Copper	ppm	ASTM D5185(m)	>25	<1		
Tin	ppm	ASTM D5185(m)	>5	0		
Antimony	ppm	ASTM D5185(m)	>5	23		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES	''	method	limit/base	current	history1	history2
Boron	nnm	ASTM D5185(m)	202	177		,_
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)	<1	0		
Manganese	ppm	ASTM D5185(m)		2		
Magnesium	ppm	1 /	<1	4		
Calcium	ppm	ASTM D5185(m) ASTM D5185(m)	<1	18		
Phosphorus	ppm	ASTM D5185(m)	1209	1090		
Zinc	ppm	ASTM D5185(m)	1	4		
Sulfur	ppm	1 /	20439	16136		
Lithium	ppm	ASTM D5185(m) ASTM D5185(m)	20439	<1		
	ppm	ASTIVI DOTOD(III)		<1		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	81		
Sodium	ppm	ASTM D5185(m)		4		
Potassium	ppm	ASTM D5185(m)	>20	6		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	VLITE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	VLITE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
<b>Emulsified Water</b>	scalar	Visual*	>0.2	NEG		
Free Water :58:46) Rev: 1	scalar	Visual*		NEG	 Submitted By: C	 harles Bergeror



## **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: GFL

: 02575480 : 5620531 Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 720 - Lafleche - Landfill Received : 11 Aug 2023 Diagnosed

: 14 Aug 2023 Diagnostician : Kevin Marson

17125 Lafleche Road, Moose Creek, ON CA K0C 1W0 Contact: Charles Bergeron cbergeron@gflenv.com

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T: (613)538-4853