

OIL ANALYSIS REPORT

Sample Rating Trend







Machine Id WL0424 Component Rear Differential Fluid SAE 30W (--- GAL)

DIAGNOSIS

Recommendation

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. The fluid was specified as (GENERIC) SAE 30W, however, a fluid match indicates that this fluid is SAE 50 Transmission/Drive Train Oil. Please confirm the oil type and grade on your next sample.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition


Viscosity of sample indicates oil is within SAE 50 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The condition of the oil is acceptable for the time in service.

				Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0077022		
Sample Date		Client Info		09 Aug 2023		
Machine Age	kms	Client Info		5420		
Oil Age	kms	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>500	178		
Chromium	ppm	ASTM D5185(m)	>3	<1		
Nickel	ppm	ASTM D5185(m)	>3	0		
Titanium	ppm	ASTM D5185(m)	>2	<1		
Silver	ppm	ASTM D5185(m)	>2	0		
Aluminum	ppm	ASTM D5185(m)	>30	3		
Lead	ppm	ASTM D5185(m)	>13	<1		
Copper	ppm	ASTM D5185(m)	>103	15		
Tin	ppm	ASTM D5185(m)	>5	0		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		4		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		4		
Manganese	ppm	ASTM D5185(m)		3		
Magnesium	ppm	ASTM D5185(m)		16		
Calcium	ppm	ASTM D5185(m)		3177		
Phosphorus	ppm	ASTM D5185(m)		998		
Zinc	ppm	ASTM D5185(m)		1117		
Sulfur	ppm	ASTM D5185(m)		4810		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>100	12		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	VLITE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual*	>.2	NEG		
Free Water	scalar	Visual*		NEG		

Contact/Location: Dean Imbeau - GFL575



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 575 - Squamish Hauling

: GFL0077022 : 02575777 : 5620828

Received Diagnosed

: 14 Aug 2023 : 14 Aug 2023 Diagnostician : Kevin Marson

38950 Queens Way, Squamish, BC CA V8B 0K8 Contact: Dean Imbeau dimbeau@gflenv.com

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T: (604)892-5604 F: (604)892-5238