

## **OIL ANALYSIS REPORT**





Machine Id 401101 Component Hydraulic System Fluid PETRO CANADA HYDREX MV 32 (--- GAL)

#### DIAGNOSIS

#### A Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.

#### Wear

All component wear rates are normal.

### Contamination

There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. Light concentration of visible dirt/debris present in the oil.

#### Fluid Condition

The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



SAMPLE INFORM	NATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0084152	GFL0039307	GFL0020811
Sample Date		Client Info		22 Aug 2023	24 Dec 2021	22 Jul 2021
Machine Age	hrs	Client Info		2221	18047	16362
Oil Age	hrs	Client Info		0	1200	1200
Oil Changed		Client Info		N/A	Changed	Changed
Sample Status				ABNORMAL	SEVERE	ABNORMAL
WEAR METALS	S	method	limit/base	current	historv1	historv2
Iron	nnm	ASTM D5185(m)	>20	12	11	5
Chromium	ppm	ASTM D5185(m)	>10	2	1	-1
Nickel	ppm	ASTM D5185(m)	>10	0	0	<1
Titanium	ppm	ASTM D5185(m)	210	د1 د1	0	0
Silver	ppm	ASTM D5185(m)		0	0	<1
Aluminum	mag	ASTM D5185(m)	>10	1	<1	<1
Lead	mag	ASTM D5185(m)	>10	<1	<1	<1
Copper	mag	ASTM D5185(m)	>75	5	6	2
Tin	ppm	ASTM D5185(m)	>10	0	<1	<1
Antimony	ppm	ASTM D5185(m)		0	<1	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
		method	limit/base	current	history1	history2
ADDITIVES		method	in the base	current	Thistory	matoryz
Boron	ppm	ASTM D5185(m)	0	2	4	4
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	<1	<1	<1
Manganese	ppm	ASTM D5185(m)	1	0	<1	0
Magnesium	ppm	ASTM D5185(m)	0	10	13	13
Calcium	ppm	ASTM D5185(m)	50	91	105	108
Phosphorus	ppm	ASTM D5185(m)	330	358	352	360
	ppm	ASTM D5185(m)	430	418	414	420
Sulfur	ppm	ASTM D5185(m)	760	//0	793	/83
Lithium	ррп	ASTINI DO 100(III)		<1	<	<
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	4	8	2
Sodium	ppm	ASTM D5185(m)		3	1	<1
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	<1
FLUID CLEANL	<b>INESS</b>	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<b>A</b> 33165	113026	▲ 10553
Particles >6µm		ASTM D7647	>1300	<u> </u>	12886	278
Particles >14µm		ASTM D7647	>160	<b>5</b> 51	55	16
Derticles . Otum						
Particles >2 1µm		ASTM D7647	>40	<u> </u>	8	6
Particles >38µm		ASTM D7647 ASTM D7647	>40 >10	▲ 178 11	8 0	6 1
Particles >38µm Particles >71µm		ASTM D7647 ASTM D7647 ASTM D7647	>40 >10 >3	▲ 178 11 1	8 0 0	6 1 0



3

Ab 28 26 Jul22/21

# **OIL ANALYSIS REPORT**



Dec24/21

22/23

25

ul22/2

	VISUAL		method	limit/base	current	history1	history2
	White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
	Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
	Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
	Silt	scalar	Visual*	NONE	NONE	NONE	NONE
	Debris	scalar	Visual*	NONE	🔺 VLITE	NONE	NONE
	Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
	Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
	Odor	scalar	Visual*	NORML	NORML	NORML	NORML
	Emulsified Water	scalar	Visual*	>0.1	NEG	NEG	NEG
	Free Water	scalar	Visual*		NEG	NEG	NEG
	FLUID PROPE	RTIES	method	limit/base	current	history1	history2
	Visc @ 40°C	cSt	ASTM D7279(m)	31.9	32.0	32.3	32.2
	SAMPLE IMAG	ES	method	limit/base	current	history1	history2
	Color				GFL0084152		
	Bottom						
	PrtFilter					no image	no image
	GRAPHS						
	Ferrous Alloys						
mqq	10 5 0 12 5 0 12 12 10 10 12 12 12 12 12 12 12 12 12 12 12 12 12	Dec24,21		Pa Hug22/23	article Filter (M	agn: 100 x) (	100 200 <sup>2004</sup> 11  100000011  1111111111
	Non-ferrous Metals	5			1	1 ·	a forthing that has
ppm	Viscosity @ 40°C	Dec24/21-		Aug22/23			
cSt (40°C)	35 Abnormal Base 30 Abnormal						

Aug22/23 -

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 573 - Vancouver Hauling Laboratory CALA Sample No. : GFL0084152 Received : 08 Sep 2023 70 Golden Drive, Lab Number : 02581174 Diagnosed : 11 Sep 2023 Coquitlam, BC ISO 17025:2017 Accredited Laboratory Unique Number : 5642239 Diagnostician : Kevin Marson CA V3K 6B5 Test Package : MOB 1 (Additional Tests: Bottom, BottomAnalysis, FilterPatch, PrtCount, PrtEduetact: Catia Klagenberg Alves To discuss this sample report, contact Customer Service at 1-800-268-2131. cklagenbergalves@gflenv.com T: Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied. F:

Dec24/21