




OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Machine Id
701079
 Component
Transmission (Auto)
 Fluid
PETRO CANADA DURADRIIVE HD SYNTHETIC ATF (--- GAL)



DIAGNOSIS

Recommendation

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition.

Wear

Les taux d'usure de tous les composants sont normaux.

Contamination

Il n'y a aucun indice de contamination dans le fluide.

Fluid Condition

L'état de le fluide est acceptable pour la durée de service.

SAMPLE INFORMATION

| | method | limit/base | current | history1 | history2 |
|---------------|-------------|-------------|--------------------|-------------|-------------|
| Sample Number | Client Info | | GFL0084388 | GFL0047495 | GFL0021285 |
| Sample Date | Client Info | | 26 Sep 2023 | 19 Oct 2022 | 24 Apr 2021 |
| Machine Age | hrs | Client Info | 138900 | 8052 | 5609 |
| Oil Age | hrs | Client Info | 0 | 2400 | 0 |
| Oil Changed | Client Info | | Not Chngd | N/A | Not Chngd |
| Sample Status | | | NORMAL | NORMAL | NORMAL |

WEAR METALS

| | method | limit/base | current | history1 | history2 | |
|-----------|--------|---------------|---------|--------------|----------|----|
| Iron | ppm | ASTM D5185(m) | >160 | 45 | 36 | 25 |
| Chromium | ppm | ASTM D5185(m) | >5 | 0 | 0 | <1 |
| Nickel | ppm | ASTM D5185(m) | >5 | <1 | 0 | <1 |
| Titanium | ppm | ASTM D5185(m) | | 0 | <1 | 0 |
| Silver | ppm | ASTM D5185(m) | >5 | <1 | 0 | <1 |
| Aluminum | ppm | ASTM D5185(m) | >50 | 11 | 18 | 24 |
| Lead | ppm | ASTM D5185(m) | >50 | 4 | 3 | 6 |
| Copper | ppm | ASTM D5185(m) | >225 | 18 | 10 | 7 |
| Tin | ppm | ASTM D5185(m) | >10 | 2 | 1 | <1 |
| Antimony | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| Vanadium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| Beryllium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| Cadmium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |

ADDITIVES

| | method | limit/base | current | history1 | history2 | |
|------------|--------|---------------|---------|--------------|----------|------|
| Boron | ppm | ASTM D5185(m) | | 21 | 70 | 73 |
| Barium | ppm | ASTM D5185(m) | | <1 | 0 | 0 |
| Molybdenum | ppm | ASTM D5185(m) | | 0 | <1 | <1 |
| Manganese | ppm | ASTM D5185(m) | | <1 | <1 | <1 |
| Magnesium | ppm | ASTM D5185(m) | | 1 | <1 | 1 |
| Calcium | ppm | ASTM D5185(m) | | 121 | 115 | 105 |
| Phosphorus | ppm | ASTM D5185(m) | | 203 | 233 | 203 |
| Zinc | ppm | ASTM D5185(m) | | 14 | 3 | 3 |
| Sulfur | ppm | ASTM D5185(m) | | 1430 | 1433 | 1287 |
| Lithium | ppm | ASTM D5185(m) | | <1 | <1 | <1 |

CONTAMINANTS


| | method | limit/base | current | history1 | history2 | |
|-----------|--------|---------------|---------|----------|----------|----|
| Silicon | ppm | ASTM D5185(m) | >20 | 5 | 7 | 11 |
| Sodium | ppm | ASTM D5185(m) | | 8 | 4 | 2 |
| Potassium | ppm | ASTM D5185(m) | >20 | 4 | <1 | 1 |

VISUAL

| | method | limit/base | current | history1 | history2 | |
|------------------|--------|------------|---------|--------------|----------|-------|
| White Metal | scalar | Visual* | NONE | NONE | NONE | NONE |
| Yellow Metal | scalar | Visual* | NONE | NONE | NONE | NONE |
| Precipitate | scalar | Visual* | NONE | NONE | NONE | NONE |
| Silt | scalar | Visual* | NONE | NONE | NONE | NONE |
| Debris | scalar | Visual* | NONE | NONE | NONE | VLITE |
| Sand/Dirt | scalar | Visual* | NONE | NONE | NONE | NONE |
| Appearance | scalar | Visual* | NORML | NORML | NORML | NORML |
| Odor | scalar | Visual* | NORML | NORML | NORML | NORML |
| Emulsified Water | scalar | Visual* | >0.1 | NEG | NEG | NEG |
| Free Water | scalar | Visual* | | NEG | NEG | NEG |




OIL ANALYSIS REPORT











| FLUID PROPERTIES | method | limit/base | current | history1 | history2 | |
|------------------|--------|---------------|---------|-------------|----------|------|
| Visc @ 40°C | cSt | ASTM D7279(m) | 36.1 | 33.2 | 33.2 | 38.2 |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---------------|--------|------------|---------|----------|----------|
|---------------|--------|------------|---------|----------|----------|



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 780 - GMA - ICI - Solid Waste
Sample No. : GFL0084388 **Received** : 12 Oct 2023 4365 boul. St-Elzear Ouest, Laval, QC
Lab Number : 02588646 **Diagnosed** : 12 Oct 2023 CA H7P 4J3
Unique Number : 5657712 **Diagnostician** : Wes Davis
Test Package : MOB 1

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

Contact: Pieces Laval
 pieces.laval@gflenv.com
 T: (450)687-3838
 F: