

# **FUEL REPORT**

### Sample Rating Trend







Machine Id SCANA Component Hydraulic System Fluid AW HYDRAULIC OIL ISO 15 (--- GAL)

## DIAGNOSIS

#### Recommendation

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

#### Wear

All component wear rates are normal.

#### Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The water content is negligible. The system and fluid cleanliness is acceptable.

#### Fluid Condition

The oil viscosity is lower than typical, possibly indicating the addition of lighter grade oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC		
Sample Date		Client Info		15 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Specific Gravity		ASTM D1298*		0.837		
Fuel Color	text	Visual Screen*		Pink		
Visc @ 40°C	cSt	ASTM D7279(m)	15	13.1		
		mothod	limit/baco	ourront	history1	history?
SOLI ON CONT				current	Thistory	mstoryz
Sulfur	ppm	ASTM D5185(m)	2500	757		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	<1.0	<1		
Sodium	ppm	ASTM D5185(m)	<0.1	<1		
Potassium	ppm	ASTM D5185(m)	<0.1	<1		
Water	%	ASTM D6304*	<0.05	0.003		
ppm Water	ppm	ASTM D6304*	<500	29.6		
FLUID CLEANL	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	1312		
Particles >6µm		ASTM D7647	>1300	252		
Particles >14µm		ASTM D7647	>160	12		
Particles >21µm		ASTM D7647	>40	4		
Particles >38µm		ASTM D7647	>10	1		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	18/15/11		
HEAVY METAL	.S	method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185(m)	<0.1	0		
Nickel	ppm	ASTM D5185(m)	<0.1	<1		
Lead	ppm	ASTM D5185(m)	<0.1	<1		
Vanadium	ppm	ASTM D5185(m)	<0.1	0		
Iron	ppm	ASTM D5185(m)	<0.1	0		
Calcium	ppm	ASTM D5185(m)	<0.1	30		
Magnesium	ppm	ASTM D5185(m)	<0.1	0		
Phosphorus	ppm	ASTM D5185(m)	<0.1	319		
Zinc	ppm	ASTM D5185(m)	<0.1	398		
SAMPLE IMAG	ES	method	limit/base	current	history1	history2
Color				1.200	no image	no image
Bottom					no image	no image
5:02:30) Rev: 1				Contact/Locatio	on: Deanne Bado	cock - TERHAM

Page 1 of 2



# **FUEL REPORT**

