

## **OIL ANALYSIS REPORT**

Sample Rating Trend







Machine Id 801133 Component Transmission (Auto) Fluid ALLISON TES 295 (--- GAL)

### DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

#### Wear

All component wear rates are normal.

#### Contamination

There is no indication of any contamination in the fluid.

#### Fluid Condition


The condition of the fluid is acceptable for the time in service.


SAMPLE INFORM	/IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0084184		
Sample Date		Client Info		12 Sep 2023		
Machine Age	hrs	Client Info		16230		
Oil Age	hrs	Client Info		600		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
WEAR METALS	5	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>160	38		
Chromium	ppm	ASTM D5185(m)	>5	0		
Nickel	ppm	ASTM D5185(m)	>5	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>5	<1		
Aluminum	ppm	ASTM D5185(m)	>50	14		
Lead	ppm	ASTM D5185(m)	>50	6		
Copper	ppm	ASTM D5185(m)	>225	9		
Tin	ppm	ASTM D5185(m)	>10	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
					matory	-
Boron	ppm	ASTM D5185(m)	150	79		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	0	3		
Calcium	ppm	ASTM D5185(m)	40	135		
Phosphorus	ppm	ASTM D5185(m)	320	244		
Zinc	ppm	ASTM D5185(m)	5	14		
Sulfur	ppm	ASTM D5185(m)	1050	1565		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	9		
Sodium	ppm	ASTM D5185(m)		4		
Potassium	ppm	ASTM D5185(m)	>20	<1		
VISUAL		method	limit/base	current	history1	history2
White Metal	agalar	Visual*	NONE	NONE		
Yellow Metal	scalar		NONE	NONE		
				NUNE		
Procinitato	scalar	Visual*				
	scalar	Visual*	NONE	NONE		
Silt	scalar scalar	Visual* Visual*	NONE NONE	NONE NONE		
Silt Debris	scalar scalar scalar	Visual* Visual* Visual*	NONE NONE NONE	NONE NONE NONE		
Silt Debris Sand/Dirt	scalar scalar scalar scalar	Visual* Visual* Visual* Visual*	NONE NONE NONE	NONE NONE NONE NONE		
Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar scalar	Visual* Visual* Visual* Visual* Visual*	NONE NONE NONE NORML	NONE NONE NONE NORE		
Silt Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar scalar scalar	Visual* Visual* Visual* Visual* Visual* Visual*	NONE NONE NONE NORML NORML	NONE NONE NONE NORML NORML	  	
Silt Debris Sand/Dirt	scalar scalar scalar scalar scalar	Visual* Visual* Visual* Visual* Visual*	NONE NONE NONE NORML	NONE NONE NONE NORML		

Report Id: GFL574 [WCAMIS] 02591493 (Generated: 10/24/2023 15:45:32) Rev: 1



# **OIL ANALYSIS REPORT**





CALA

ISO 17025:2017 Accredited Laboratory

.