


OIL ANALYSIS REPORT



NORMAL



Machine Id **26035ZA331**

Component

Rear Diesel Engine

PETRO CANADA DURON HP 15W40 (--- L'

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition


The condition of the oil is acceptable for the time in service.

R)				Oct2023		
SAMPLE INFO	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC0075225		
Sample Date		Client Info		05 Oct 2023		
Machine Age	hrs	Client Info		7566		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINA	TION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0		
Water		WC Method	>0.2	NEG		
Glycol		WC Method		NEG		
WEAR META	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>165	34		
Chromium	ppm	ASTM D5185(m)	>5	1		
Nickel	ppm	ASTM D5185(m)	>4	<1		
Titanium	ppm	ASTM D5185(m)	>2	0		
Silver	ppm	ASTM D5185(m)	>2	<1		
Aluminum	ppm	ASTM D5185(m)	>20	1		
Lead	ppm	ASTM D5185(m)	>150	7		
Copper	ppm	ASTM D5185(m)	>90	6		
Tin	ppm	ASTM D5185(m)	>5	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	11		
Barium	ppm	ASTM D5185(m)	0	<1		
Molybdenum	ppm	ASTM D5185(m)	60	63		
Manganese	ppm	ASTM D5185(m)	0	0		
Magnesium	ppm	ASTM D5185(m)	1010	1014		
Calcium	ppm	ASTM D5185(m)	1070	1104		
Phosphorus	ppm	ASTM D5185(m)	1150	1009		
Zinc	ppm	ASTM D5185(m)	1270	1233		
Sulfur	ppm	ASTM D5185(m)	2060	2395		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>35	8		
Sodium	ppm	ASTM D5185(m)		5		
Potassium	ppm	ASTM D5185(m)	>20	<1		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>7.5	1.9		
Nitration	Abs/cm	ASTM D7624*	>20	11.9		
Sulfation	Abs/.1mm	ASTM D7415*	>30	27.4		



OIL ANALYSIS REPORT





22.6

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: PC0075225 +02603442

Recieved Diagnosed

: 15 Dec 2023 : 15 Dec 2023 Diagnostician : Wes Davis

: 5696527 **Test Package**: MOB 1 (Additional Tests: KV40, VI, Visual) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

TORONTO FIRE SERVICES

40 TORYORK DRIVE TORONTO, ON CA M9L 1X6

Contact: Antonio Rodrigues antonio.rodrigues@toronto.ca T:

F: (416)338-9207