






OIL ANALYSIS REPORT





: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Laboratory CALA **Sample No.** : PC0085494 : 02 Feb 2024 Received ISO 17025:2017 Lab Number : 02613136 : 05 Feb 2024 **Tested** Accredited Unique Number : 5722231 Diagnosed: 05 Feb 2024 - Bill Quesnel Laboratory

Test Package : PLANT (Additional Tests: FT-IR, FT-IR(Diff), KV100, TAN Man, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

NuVista Energy 10508 67 Ave, #201 Grande Prairie, AB **CA T8W 0K8** Contact: Eldon Weaver eweaver@nvaenergy.com

T:

F:

Submitted By: Kris Dickmann