







OIL ANALYSIS REPORT







VISUAL	method	limit/base	current	history1	history2	
White Metal	scalar	Visual*	NONE	NONE	---	---
Yellow Metal	scalar	Visual*	NONE	NONE	---	---
Precipitate	scalar	Visual*	NONE	NONE	---	---
Silt	scalar	Visual*	NONE	NONE	---	---
Debris	scalar	Visual*	NONE	NONE	---	---
Sand/Dirt	scalar	Visual*	NONE	NONE	---	---
Appearance	scalar	Visual*	NORML	NORML	---	---
Odor	scalar	Visual*	NORML	NORML	---	---
Emulsified Water	scalar	Visual*	>0.1	NEG	---	---
Free Water	scalar	Visual*		NEG	---	---

FLUID PROPERTIES	method	limit/base	current	history1	history2	
Visc @ 40°C	cSt	ASTM D7279(m)	31.5	32.6	---	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **GFL Environmental - 310 - Winnipeg**
Sample No. : GFL0107892 **Received** : 26 Mar 2024 **#360 - 555 Hervo Street,**
Lab Number : **02624725** **Tested** : 27 Mar 2024 **Winnipeg, MB**
Unique Number : 5749844 **Diagnosed** : 27 Mar 2024 - Kevin Marson **CA R3T 3L6**
Test Package : MOB 1 (Additional Tests: PrtCount) **Contact: Joshua Lourenco**
To discuss this sample report, contact Customer Service at 1-800-268-2131. **jlourenco@gflenv.com**
Test denoted () outside scope of accreditation, (m) method modified, (e) tested at external lab.* **T: (204)987-9600**
Validity of results and interpretation are based on the sample and information as supplied. **F:**