


OIL ANALYSIS REPORT

Gas Compression [450296476]

Compressor (LP) - Lubrication System (S/N Sample Tag XX-23001-S1)

Lube System

PETRO CANADA TURBOFLO XL32 (7600 LTR)



DIAGNOSIS

Recommendation

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MAR 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.

Wear

Component wear rates appear to be normal (unconfirmed).

Contamination

There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code.


Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.


SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC0081647	PC0082748	PC0076672
Sample Date		Client Info		28 Mar 2024	01 Mar 2024	29 Jan 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>20	0	<1	0
Chromium	ppm	ASTM D5185(m)	>10	0	0	0
Nickel	ppm	ASTM D5185(m)	>10	0	<1	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>10	0	<1	<1
Lead	ppm	ASTM D5185(m)	>20	0	0	0
Copper	ppm	ASTM D5185(m)	>20	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>10	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1	0	0
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)	0	0	0	0
Magnesium	ppm	ASTM D5185(m)	0	<1	<1	<1
Calcium	ppm	ASTM D5185(m)		0	0	<1
Phosphorus	ppm	ASTM D5185(m)	5	4	2	3
Zinc	ppm	ASTM D5185(m)	0	2	2	<1
Sulfur	ppm	ASTM D5185(m)	750	633	672	654
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	0	<1	0
Sodium	ppm	ASTM D5185(m)		<1	<1	0
Potassium	ppm	ASTM D5185(m)	>20	0	<1	<1



OIL ANALYSIS REPORT



FLUID CLEANL	INESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647		44515	39210	1244
Particles >6µm		ASTM D7647	>2500	▲ 13329	▲ 13457	390
Particles >14µm		ASTM D7647	>320	▲ 1038	▲ 1081	47
Particles >21µm		ASTM D7647		<u>△</u> 275	<u>△</u> 274	16
Particles >38µm		ASTM D7647	>20	21	19	2
Particles >71µm		ASTM D7647		3	2	0
Oil Cleanliness		ISO 4406 (c)	>/18/15	<u>^</u> 23/21/17	<u>22/21/17</u>	17/16/13
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.04	0.08	0.08	0.06
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.05	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	33.86	33.8	34.1	34.0
Visc @ 100°C	cSt	ASTM D7279(m)	5.60	5.7	5.7	5.7
Viscosity Index (VI)	Scale	ASTM D2270*	101	108	106	107
SAMPLE IMAG	iES	method	limit/base	current	history1	history2
Color						
Bottom						





Laboratory Sample No.

Lab Number : 02631144 Unique Number : 5772297

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: PC0081647 Received : 24 Apr 2024 **Tested** : 25 Apr 2024 Diagnosed : 25 Apr 2024 - Kevin Marson

Test Package: MAR 2 (Additional Tests: KV100, PQ, TAN Man, VI) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Suncor - Terra Nova Projects Scotia Centre, 235 Water Strret

St. John's, NL CA A1C 1B6

Contact: Josh Hynes joshynes@suncor.com T: (709)778-3575

F: (709)724-2835