


OIL ANALYSIS REPORT

Water Injection

Pump Sea Water Injection (A) - Lube System (S/N Sample Tag PA-29002A-S1)

Pump

PETRO CANADA TURBOFLO 46 (1264 LTR)



DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you follow the water drain-off procedure for this component. We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. Free water present. The system cleanliness is above the acceptable limit for the target ISO 4406 cleanliness code.


Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC	PC	PC
Sample Date		Client Info		09 Apr 2024	23 Mar 2024	20 Feb 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	SEVERE	NORMAL
CONTAMINATI	ION	method	limit/base	current	history1	history2
Water		WC Method	>.1	NEG	NEG	NEG
WEAR METALS	S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>75	0	0	0
Chromium	ppm	ASTM D5185(m)	>5	0	0	0
Nickel	ppm	ASTM D5185(m)		0	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>5	0	0	<1
Lead	ppm	ASTM D5185(m)	>10	0	0	<1
Copper	ppm	ASTM D5185(m)	>15	<1	<1	<1
Tin	ppm	ASTM D5185(m)		0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1	<1	0
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)	0	0	0	0
Magnesium	ppm	ASTM D5185(m)	0	<1	0	0
Calcium	ppm	ASTM D5185(m)	0	0	0	0
Phosphorus	ppm	ASTM D5185(m)	110	151	147	153
Zinc	ppm	ASTM D5185(m)	0.0	1	<1	<1
Sulfur	ppm	ASTM D5185(m)		257	184	188
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	1	1	2
Sodium	ppm	ASTM D5185(m)		0	0	0
Potassium	ppm	ASTM D5185(m)	>20	0	0	<1



OIL ANALYSIS REPORT



FLUID CLEANL	INITOO	method	limit/base	a	la i a t a m . d	history.O
	IINESS		IIIIII/base	current	history1	history2
Particles >4µm		ASTM D7647		31360	32667	190
Particles >6µm		ASTM D7647	>1300	<u> </u>	▲ 12584	53
Particles >14μm		ASTM D7647	>160	<u>^</u> 327	1 447	6
Particles >21μm		ASTM D7647	>40	51	4 18	2
Particles >38µm		ASTM D7647	>10	4	<u>4</u> 1	1
Particles >71µm		ASTM D7647		0	3	1
Oil Cleanliness		ISO 4406 (c)	>/17/14	22/20/16	2 2/21/18	15/13/10
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.05	0.04	0.06	0.06
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	VLITE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	VLITE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>.1	.5%	NEG	NEG
Free Water	scalar	Visual*		1 %	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	46.6	45.1	45.1	45.3
Visc @ 100°C	cSt	ASTM D7279(m)	7.04	6.7	6.8	6.8
Viscosity Index (VI)	Scale	ASTM D2270*	107	100	104	104
SAMPLE IMAG	ES	method	limit/base	current	history1	history2
Color						
00101						
Б.::						0
Bottom						





Laboratory

Sample No.

: PC Lab Number : 02631669 Unique Number : 5772822

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 26 Apr 2024

Tested : 29 Apr 2024 Diagnosed : 29 Apr 2024 - Kevin Marson Test Package: MAR 2 (Additional Tests: KV100, PQ, TAN Man, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Suncor - Terra Nova Projects

Scotia Centre, 235 Water Strret St. John's, NL CA A1C 1B6

Contact: Josh Hynes joshynes@suncor.com T: (709)778-3575

F: (709)724-2835