

901148 - TRANSMISSION (AUTO)

Sample No: GFL0111770

Oil Type: DEXRON III

SAMPLE INFORMATION

Sample Number	GFL0111770	---	---	---
Sample Date	13 Apr 2024	---	---	---
Machine Hours	9413	---	---	---
Oil Hours	3100	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	NORMAL	---	---	---

GFL Environmental - 557 - Edson

6615 - 4th Ave,

Edson, AB

CA T7E 1M5

Contact: GFL Tech

wcgfldemo@gmail.com

T:

F:

OIL CONDITION

Visc @ 40°C cSt ■ **31.2** --- --- ---

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 9	---	---	---
Sodium	ppm	■ 10	---	---	---
Potassium	ppm	■ 3	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

WEAR METALS

Iron	ppm	■ 138	---	---	---
Copper	ppm	■ 42	---	---	---
Lead	ppm	■ 10	---	---	---
Tin	ppm	■ 4	---	---	---
Aluminum	ppm	■ 54	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	■ 0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 2	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	■ 84	---	---	---
Magnesium	ppm	■ 1	---	---	---
Zinc	ppm	■ 7	---	---	---
Phosphorus	ppm	■ 232	---	---	---
Barium	ppm	■ <1	---	---	---
Boron	ppm	■ 73	---	---	---

Depot: GFL557

Unique No: 5773979

Signed: Wes Davis

Report Date: 02 May 2024

Contact/Location: GFL Tech - GFL557

GRAPHS

