






# OIL ANALYSIS REPORT




| VISUAL           | method | limit/base | current | history1 | history2 |     |
|------------------|--------|------------|---------|----------|----------|-----|
| White Metal      | scalar | Visual*    | NONE    | NONE     | ---      | --- |
| Yellow Metal     | scalar | Visual*    | NONE    | NONE     | ---      | --- |
| Precipitate      | scalar | Visual*    | NONE    | NONE     | ---      | --- |
| Silt             | scalar | Visual*    | NONE    | NONE     | ---      | --- |
| Debris           | scalar | Visual*    | NONE    | NONE     | ---      | --- |
| Sand/Dirt        | scalar | Visual*    | NONE    | NONE     | ---      | --- |
| Appearance       | scalar | Visual*    | NORML   | NORML    | ---      | --- |
| Odor             | scalar | Visual*    | NORML   | NORML    | ---      | --- |
| Emulsified Water | scalar | Visual*    | >0.1    | NEG      | ---      | --- |
| Free Water       | scalar | Visual*    |         | NEG      | ---      | --- |

| FLUID PROPERTIES     | method | limit/base    | current | history1 | history2 |
|----------------------|--------|---------------|---------|----------|----------|
| Visc @ 40°C          | cSt    | ASTM D7279(m) | 46.8    | ---      | ---      |
| Visc @ 100°C         | cSt    | ASTM D7279(m) | 8.1     | ---      | ---      |
| Viscosity Index (VI) | Scale  | ASTM D2270*   | 146     | ---      | ---      |

| SAMPLE IMAGES | method | limit/base | current  | history1 | history2 |
|---------------|--------|------------|--|----------|----------|
| Color         |        |            |   | no image | no image |
| Bottom        |        |            |  | no image | no image |

## GRAPHS



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : PC0082543 **Received** : 15 May 2024  
**Lab Number** : 02635687 **Tested** : 15 May 2024  
**Unique Number** : 5776840 **Diagnosed** : 15 May 2024 - Kevin Marson  
**Test Package** : MOB 1 ( Additional Tests: KV100, VI )

**Les Excavations Payette**  
 7900 Rue Bombardier  
 Anjou, QC  
 CA H1J 1A4  
 Contact: Service  
 mcheynemand@excavationpayette.com  
 T: (438)226-8820  
 F: (514)322-1770

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.