

OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id
NO UNIT PC0087789
Component
Unknown Component
Fluid
{not provided} (--- GAL)

DIAGNOSIS

Recommendation

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Please provide more complete information on your next sample.



Contamination

Insufficient sample was received to conduct all the routine laboratory tests.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|--------------------|-------------|-------------|------------|--------------------|----------|----------|
| Sample Number | Client Info | | | PC0087789 | --- | --- |
| Sample Date | Client Info | | | 22 May 2024 | --- | --- |
| Machine Age | hrs | Client Info | | 0 | --- | --- |
| Oil Age | hrs | Client Info | | 0 | --- | --- |
| Oil Changed | Client Info | | | N/A | --- | --- |
| Sample Status | | | | NORMAL | --- | --- |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---------------|-----------|--------|------------|------------|----------|----------|
| Water | WC Method | | | NEG | --- | --- |

| VISUAL | | method | limit/base | current | history1 | history2 |
|--------------|--------|---------|------------|--------------|----------|----------|
| White Metal | scalar | Visual* | NONE | NONE | --- | --- |
| Yellow Metal | scalar | Visual* | NONE | NONE | --- | --- |
| Precipitate | scalar | Visual* | NONE | NONE | --- | --- |
| Silt | scalar | Visual* | NONE | VLITE | --- | --- |
| Debris | scalar | Visual* | NONE | NONE | --- | --- |
| Sand/Dirt | scalar | Visual* | NONE | NONE | --- | --- |
| Appearance | scalar | Visual* | NORML | NORML | --- | --- |
| Odor | scalar | Visual* | NORML | NORML | --- | --- |

| SAMPLE IMAGES | | method | limit/base | current | history1 | history2 |
|---------------|--|--------|------------|---|----------|----------|
| Color | | | |  | no image | no image |
| Bottom | | | |  | no image | no image |

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC0087789
Lab Number : 02637327
Unique Number : 5786489
Test Package : TEST (Additional Tests: ICP)

Received : 23 May 2024
Tested : 24 May 2024
Diagnosed : 24 May 2024 - Kevin Marson

Powercor Manufacturing - Linamar
545 Elmira Road
Guelph, ON
CA N1K 1C2
Contact: Manthan Rathi
manthan.rathi@linamar.com
T: (226)326-0125
F: (226)326-0124

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.