


OIL ANALYSIS REPORT



R72140 Component

Diesel Engine

PETRO CANADA DURON HP 15W40 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

)N HP 15W4U (-	GAL)			Jun 2024		
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0080163		
Sample Date		Client Info		28 Jun 2024		
Machine Age	hrs	Client Info		2821		
Oil Age	hrs	Client Info		600		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINA	TION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Nater		WC Method	>0.2	NEG		
WEAR METAI	LS	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185(m)	>80	77		
Chromium	ppm	ASTM D5185(m)	>5	2		
Nickel	ppm	ASTM D5185(m)	>2	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>3	0		
Aluminum	ppm	ASTM D5185(m)	>30	4		
Lead	ppm	ASTM D5185(m)	>30	0		
Copper	ppm	ASTM D5185(m)	>150	3		
Γin	ppm	ASTM D5185(m)	>5	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	6		
Barium	ppm	ASTM D5185(m)	0	<1		
Molybdenum	ppm	ASTM D5185(m)	60	60		
Manganese	ppm	ASTM D5185(m)	0	1		
Magnesium	ppm	ASTM D5185(m)	1010	915		
Calcium	ppm	ASTM D5185(m)	1070	1113		
Phosphorus	ppm	ASTM D5185(m)	1150	945		
Zinc	ppm	ASTM D5185(m)	1270	1183		
Sulfur	ppm	ASTM D5185(m)	2060	2232		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	6		
Sodium	ppm	ASTM D5185(m)		14		
Potassium	ppm	ASTM D5185(m)	>20	11		
Glycol	%	ASTM D7922*		0.0		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	1.4		
Nitration	Abs/cm	ASTM D7624*	>20	15.2		
Sulfation	Abs/.1mm	ASTM D7415*	>30	30.1		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : GFL0080163

Lab Number : 02647557 Unique Number : 5813109

Diagnosed : 15 Jul 2024 - Kevin Marson

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Test Package : MOB 1 (Additional Tests: Glycol, Visual) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Validity of results and interpretation are based on the sample and information as supplied.

GFL Environmental - 577 - First Class 8540 Chilliwack Mountain Rd, Chilliwack, BC **CA V2R 3W8**

Contact: Derek Jessop djessop@gflenv.com T: (604)798-5301

: 12 Jul 2024

: 12 Jul 2024

Received

Tested

Report Id: GFL577 [WCAMIS] 02647557 (Generated: 07/15/2024 08:21:08) Rev: 1

Submitted By: Derek Jessop