OIL ANALYSIS REPORT

LUBE 360 DIAGNOSTICS

Sample Rating Trend

Jul2024

NORMAL ✓

Machine Id
M/C 509
Component
Unknown Component
Fluid
{not provided} (--- GAL)

DIAGNOSIS

Recommendation

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Please provide more complete information on your next sample.

SAMPLE INFORMATION	method	limit/base	current	history1	history2
Sample Number		Client Info	**PC**	---	---
Sample Date		Client Info	**14 Jul 2024**	---	---
Machine Age	hrs	Client Info	**0**	---	---
Oil Age	hrs	Client Info	**0**	---	---
Oil Changed		Client Info	**N/A**	---	---
Sample Status			**NORMAL**	---	---

CONTAMINANTS	method	limit/base	current	history1	history2
Water	%	ASTM D6304*	**93.8**	---	---
ppm Water	ppm	ASTM D6304*	**938000**	---	---

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	**NONE**	---	---
Yellow Metal	scalar	Visual*	NONE	**NONE**	---	---
Precipitate	scalar	Visual*	NONE	**NONE**	---	---
Silt	scalar	Visual*	NONE	**NONE**	---	---
Debris	scalar	Visual*	NONE	**NONE**	---	---
Sand/Dirt	scalar	Visual*	NONE	**NONE**	---	---
Appearance	scalar	Visual*	NORML	**NORML**	---	---
Odor	scalar	Visual*	NORML	**NORML**	---	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image

GRAPHS

Water (KF)

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

ISO 17025:2017
Accredited
Laboratory

CALA