


OIL ANALYSIS REPORT



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC
Lab Number : 02647979
Unique Number : 5813531
Test Package : TEST (Additional Tests: KF)

Powercor Manufacturing - Linamar
 545 Elmira Road
 Guelph, ON
 CA N1K 1C2
 Contact: Manthan Rathi
 manthan.rathi@linamar.com
 T: (226)326-0125
 F: (226)326-0124

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.