


# **PROBLEM SUMMARY**

Sample Rating Trend



Machine Id **2126999** 

Component **Hydraulic System** 

PETRO CANADA HYDREX MV 36 (--- QTS)

# **COMPONENT CONDITION SUMMARY**

No relevant graphs to display

#### RECOMMENDATION

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	NORMAL	NORMAL		
Debris	scalar	*Visual	NONE	MODER	NONE	NONE		

**Customer Id: PERSALMD** Sample No.: PCA0092455 Lab Number: 05843781 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

## **RECOMMENDED ACTIONS**

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

# HISTORICAL DIAGNOSIS

#### 15 Oct 2022 Diag: Don Baldridge





Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



#### 27 Aug 2022 Diag: Doug Bogart

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## 30 Jun 2022 Diag: Doug Bogart

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.





# **OIL ANALYSIS REPORT**

#### Sample Rating Trend

# **VIS DEBRIS**

Machine Id 2126999

Component

**Hydraulic System** 

PETRO CANADA HYDREX MV 36 (--- QTS)

## **DIAGNOSIS**

#### Recommendation

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

Moderate concentration of visible dirt/debris present in the oil.

#### **Fluid Condition**

The condition of the oil is acceptable for the time in service.

		Jan2022	Mar2022 May2022	Jun2022 Aug2022 Oct2022	May2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0092455	PCA0076965	PCA0075921
Sample Date		Client Info		07 May 2023	15 Oct 2022	27 Aug 2022
Machine Age	mls	Client Info		191708	112753	91402
Oil Age	mls	Client Info		24000	15000	0
Oil Changed		Client Info		Changed	Not Changd	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	7	0	<1
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		<1	<1	1
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>20	<1	0	<1
Lead	ppm	ASTM D5185m	>20	0	0	<1
Copper	ppm	ASTM D5185m	>20	2	0	<1
Tin	ppm	ASTM D5185m	>20	0	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	5	0	7
Barium	ppm	ASTM D5185m	0	0	0	2
Molybdenum	ppm	ASTM D5185m	0	2	<1	4
Manganese	ppm	ASTM D5185m	1	0	0	0
Magnesium	ppm	ASTM D5185m	0	27	11	51
Calcium	ppm	ASTM D5185m	135	135	80	143
Phosphorus	ppm	ASTM D5185m	236	377	365	373
Zinc	ppm	ASTM D5185m	317	460	473	471
Sulfur	ppm	ASTM D5185m	561	1528	1311	998
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	2	<1	0
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	1	0	1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	▲ MODER	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
<b>Emulsified Water</b>	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2

Visc @ 40°C

cSt


ASTM D445 32.25

33.4

35.4





# **OIL ANALYSIS REPORT**






#### **GRAPHS**











Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10467888 Test Package : FLEET

: PCA0092455 : 05843781

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 10 May 2023 Diagnosed : 15 May 2023 Diagnostician : Don Baldridge

**PERDUE FARMS - SALISBURY** 7036 ZION CHURCH ROAD

SALISBURY, MD US 21802

Contact: RICHARD O'NEAL richard.oneal@perdue.com

T: (410)543-3628 F: (410)341-2164

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)