


PROBLEM SUMMARY

Sample Rating Trend





Machine Id **2629** Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (30 GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. No other corrective action is recommended at this time.

PROBLEMATIC TEST RESULTS									
Sample Status				ABNORMAL	NORMAL	NORMAL			
Fuel	%	ASTM D3524	>5	4.6	<1.0	<1.0			
Visc @ 100°C	cSt	ASTM D445	15.4	12.1	13.2	13.6			

Customer Id: GFL035 Sample No.: GFL0071553 Lab Number: 05888807 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Check Fuel/injector System			?	We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS

09 May 2023 Diag: Wes Davis





Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



29 Dec 2022 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



11 Nov 2022 Diag: Wes Davis

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend







Machine Id 2629 Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (30 GAL)

DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. No other corrective action is recommended at this time.

Wear

All component wear rates are normal.

Contamination

Light fuel dilution occurring. No other contaminants were detected in the oil.


▲ Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.


GAL)		in2016 Dec20	16 Aug2017 Mar2018 J	ul2019 Dec2020 Jun2021 Feb202	2 May2023	
SAMPLE INFOR	MATION	method	limit/base	current	history 1	history 2
Sample Number		Client Info		GFL0071553	GFL0071539	GFL0061674
Sample Date		Client Info		21 Jun 2023	09 May 2023	29 Dec 2022
Machine Age	hrs	Client Info		16576	16576	16576
Oil Age	hrs	Client Info		600	600	600
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history 1	history 2
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>100	14	19	21
Chromium	ppm	ASTM D5185m	>20	3	2	2
Nickel	ppm	ASTM D5185m	>4	2	2	<1
Titanium	ppm	ASTM D5185m		2	0	0
Silver	ppm	ASTM D5185m	>3	1	<1	0
Aluminum	ppm	ASTM D5185m	>20	6	1	3
Lead	ppm	ASTM D5185m	>40	5	2	<1
Copper	ppm	ASTM D5185m	>330	2	<1	1
Tin	ppm	ASTM D5185m	>15	2	<1	<1
Vanadium	ppm	ASTM D5185m		1	<1	0
Cadmium	ppm	ASTM D5185m		2	0	0
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m	0	23	4	13
Barium	ppm	ASTM D5185m	0	18	0	0
Molybdenum	ppm	ASTM D5185m	60	49	58	63
Manganese	ppm	ASTM D5185m	0	2	<1	<1
Magnesium	ppm	ASTM D5185m	1010	633	895	893
Calcium	ppm	ASTM D5185m	1070	776	977	1139
Phosphorus	ppm	ASTM D5185m	1150	733	986	1035
Zinc	ppm	ASTM D5185m	1270	904	1219	1160
Sulfur	ppm	ASTM D5185m	2060	2580	3516	3375
CONTAMINAN	TS	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	7	7	9
Sodium	ppm	ASTM D5185m		33	5	8
Potassium	ppm	ASTM D5185m	>20	8	3	0
Fuel	%	ASTM D3524	>5	4.6	<1.0	<1.0
INFRA-RED		method	limit/base	current	history 1	history 2
Soot %	%	*ASTM D7844	>3	0.4	0.5	0.5
Nitration	Abs/cm	*ASTM D7624		9.0	9.4	9.7
Sulfation	Abs/.1mm	*ASTM D7415	>30	20.3	20.4	21.0
FLUID DEGRAI	DATION	method	limit/base	current	history 1	history 2
Oxidation	Abs/.1mm	*ASTM D7414	>25	16.3	17.7	17.8
	mg KOH/g		9.8	8.8	8.8	9.1
Base Number (BN)						



OIL ANALYSIS REPORT










VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROPI	EHIIES	method	iiiiii/base	current	flistory i	nistory i
Visc @ 100°C	cSt	ASTM D445	15.4	<u> </u>	13.2	13.6

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: 05888807

: GFL0071553 : 10539290

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 03 Jul 2023 Diagnosed

: 06 Jul 2023 Diagnostician : Wes Davis

Test Package : FLEET (Additional Tests: FuelDilution, PercentFuel) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 035 - Greensboro

1236 Elon Place High Point, NC US 27263

Contact: JORGE COSTA jorge.costa@gflenv.com T: (336)668-3712 F: