


OIL ANALYSIS REPORT









Machine Id **425101**

Component

1 Transmission (Auto)

PETRO CANADA DuraDriv

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

SAMPLE INFOR	MATION	method	limit/base	current	history 1	history
Sample Number		Client Info		GFL0085317		
Sample Date		Client Info		26 Jun 2023		
Machine Age	hrs	Client Info		15242		
Oil Age	hrs	Client Info		307		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
WEAR METAL	.S	method	limit/base	current	history 1	history
ron	ppm	ASTM D5185m	>160	54		
Chromium	ppm	ASTM D5185m	>5	0		
Nickel	ppm	ASTM D5185m	>5	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>5	0		
Aluminum	ppm	ASTM D5185m	>50	2		
_ead	ppm	ASTM D5185m	>50	<1		
Copper	ppm	ASTM D5185m	>225	2		
- Tin	ppm	ASTM D5185m	>10	0		
/anadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history 1	history
Boron	ppm	ASTM D5185m		94		
Barium	ppm	ASTM D5185m		2		
Nolybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		<1		
/lagnesium	ppm	ASTM D5185m		2		
Calcium	ppm	ASTM D5185m		123		
Phosphorus	ppm	ASTM D5185m		222		
Zinc	ppm	ASTM D5185m		6		
Bulfur	ppm	ASTM D5185m		1993		
CONTAMINAN	ITS	method	limit/base	current	history 1	history
Silicon	ppm	ASTM D5185m	>20	5		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	<1		
VISUAL		method	limit/base	current	history 1	history
Vhite Metal	scalar	*Visual	NONE	NONE		
'ellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	LIGHT		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
ree Water	scalar	*Visual		NEG		





OIL ANALYSIS REPORT






GRAPHS









Certificate L2367

Laboratory Sample No. Lab Number

: 05890984 Unique Number : 10546794 Test Package : FLEET

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0085317 Received Diagnosed

: 05 Jul 2023 : 07 Jul 2023 Diagnostician : Don Baldridge GFL Environmental - 958 - Tri County HC Morton

1090 W. Jefferson St. Morton, IL US 61550

Contact: Bryan Link

blink@gflenv.com T:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: