

# **OIL ANALYSIS REPORT**

Antimony

Vanadium

### Sample Rating Trend

## NORMAL



# Area [98044085]

KR-GR-003451 - LOADER RACK CONVEYOR - SOUTH (S/N STUFF C - 11513133)

Component

Gearbox

SCHAEFFER 293A SUPREME GEAR LUBE NO TACK 220 (--- GAL

## DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

There is no indication of any contamination in the oil

#### **Fluid Condition**

The condition of the oil is acceptable for the time in service.

IIH (5/N 51UFF C - 11)	513133)					
E NO TACK 220 (	- GAL)		Jui2020	Jui2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0099360	PCA0022184	
Sample Date		Client Info		07 Jul 2023	08 Jul 2020	
Machine Age	hrs	Client Info		0	0	
Oil Age Oil Changed	hrs	Client Info		0 N/A	0 N/A	
Sample Status				NORMAL	ATTENTION	
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	12	1	
Chromium	ppm	ASTM D5185m	>15	0	<1	
Nickel	ppm	ASTM D5185m	>15	0	<1	
Titanium	ppm	ASTM D5185m		<1	0	
Silver	ppm	ASTM D5185m		0	0	
Aluminum	ppm	ASTM D5185m	>25	<1	2	
Lead	ppm	ASTM D5185m	>100	0	1	
Copper	ppm	ASTM D5185m	>200	<1	<1	
Tin	ppm	ASTM D5185m	>25	0	0	

Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		2	23	
Barium	ppm	ASTM D5185m		0	0	
Molybdenum	ppm	ASTM D5185m		42	218	
Manganese	ppm	ASTM D5185m		3	<1	
Magnesium	ppm	ASTM D5185m		0	1	
Calcium	ppm	ASTM D5185m		6	71	
Phosphorus	ppm	ASTM D5185m		521	669	
Zinc	ppm	ASTM D5185m		0	44	
Sulfur	ppm	ASTM D5185m		4522	11844	
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	4	7	

0

ASTM D5185m >5

ppm


ppm


Sodium	ppm	ASTM D5185m		3	1	
Potassium	ppm	ASTM D5185m	>20	0	0	
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	NONE	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
<b>Emulsified Water</b>	scalar	*Visual	>0.2	NEG	NEG	
Free Water	scalar	*Visual		NEG	NFG	


8




## **OIL ANALYSIS REPORT**











Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10551244 Test Package : IND 1

: PCA0099360 : 05895434

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 11 Jul 2023 Diagnosed : 13 Jul 2023 Diagnostician : Don Baldridge

KraftHeinz - Kirksville - Plant 8333 PCA 2504 INDUSTRIAL DR

KIRKSVILLE, MO US 63501

Contact: WALLACE WARD wallace.ward@kraftheinzcompany.com

T: (660)627-1031 F: (660)627-5887

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)