


OIL ANALYSIS REPORT

(11657Z) Walgreens [Walgreens] 136A61453

Diesel Engine

PETRO CANADA DURON SHP 10W30 (11 GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0091524	PCA0091474	PCA0087954
Sample Date		Client Info		21 Jun 2023	31 Mar 2023	19 Jan 2023
Machine Age	mls	Client Info		417398	388066	361612
Oil Age	mls	Client Info		50000	26454	50000
Oil Changed		Client Info		Changed	Oil Added	Changed
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	31	11	15
Chromium	ppm	ASTM D5185m	>5	2	1	1
Nickel	ppm	ASTM D5185m	>2	0	<1	<1
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>30	20	9	9
Lead	ppm	ASTM D5185m	>30	0	0	<1
Copper	ppm	ASTM D5185m	>150	9	4	5
Tin	ppm	ASTM D5185m	>5	<1	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	<1	1	0
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	50	90	62	60
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	950	1314	975	948
Calcium	ppm	ASTM D5185m	1050	1511	1095	1151
Phosphorus	ppm	ASTM D5185m	995	1430	1056	962
Zinc	ppm	ASTM D5185m	1180	1759	1273	1268
Sulfur	ppm	ASTM D5185m	2600	4182	3544	3056
CONTAMINAN		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	6	2	4
Sodium	ppm	ASTM D5185m		0	2	<1
Potassium	ppm	ASTM D5185m	>20	5	2	6
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	1.2	0.6	1
Nitration	Abs/cm	*ASTM D7624	>20	9.6	7.6	9.3
Sulfation	Abs/.1mm	*ASTM D7415	>30	22.9	17.3	21.4
FLUID DEGRAD	NOITAC	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	19.4	14.5	17.4
Base Number (BN)	mg KOH/g	ASTM D2896		6.0	7.4	6.8




OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


L LOID PROPI	EHILO	method			riistory i	HISTORYZ
Visc @ 100°C	cSt	ASTM D445	12.00	11.6	11.5	11.6

GRAPHS











Certificate L2367

Laboratory Sample No.

Lab Number Unique Number : 10559310

: PCA0091524 : 05897954

Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 13 Jul 2023

Diagnosed : 14 Jul 2023 Diagnostician : Doug Bogart

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Transervice - Shop 1361 - Berkeley-Windsor

4400 State Road 19 Windsor, WI US 53598

Contact: Mike Hurda mhurda@transervice.com

T: (608)846-2726 F: (608)846-0389