

PROBLEM SUMMARY





Machine Id
413006
Component
Diesel Engine
Fluid

PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	NORMAL	NORMAL	
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	2.5	7.9	7.9	

Customer Id: GFL094 Sample No.: GFL0072198 Lab Number: 05918358 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS

29 May 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



07 Mar 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

06 Dec 2022 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT


Sample Rating Trend

DEGRADATION



Machine Id 413006 Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)





DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition


The BN level is low. The condition of the oil is acceptable for the time in service.

W 3HP 13W40 (- GAL)	Oct2022	Dec2022	Mar2023 May2023	Aug2023	
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0072198	GFL0072201	GFL0034192
Sample Date		Client Info		02 Aug 2023	29 May 2023	07 Mar 2023
Machine Age	hrs	Client Info		2431	1950	1424
Oil Age	hrs	Client Info		600	600	600
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	8	10	15
Chromium	ppm	ASTM D5185m	>20	<1	<1	1
Nickel	ppm	ASTM D5185m	>5	<1	2	4
Titanium	ppm	ASTM D5185m	>2	<1	0	0
Silver	ppm	ASTM D5185m	>2	<1	<1	<1
Aluminum	ppm	ASTM D5185m	>20	4	6	10
Lead	ppm	ASTM D5185m	>40	0	<1	<1
Copper	ppm	ASTM D5185m	>330	3	6	8
Tin	ppm	ASTM D5185m	>15	<1	1	1
Vanadium	ppm	ASTM D5185m		<1	<1	<1
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	5	7	6
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	61	62	67
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	942	951	867
Calcium	ppm	ASTM D5185m	1070	1106	1092	1131
Phosphorus	ppm	ASTM D5185m	1150	993	1059	985
Zinc	ppm	ASTM D5185m	1270	1234	1328	1204
Sulfur	ppm	ASTM D5185m	2060	3408	3266	2962
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	4	4	4
Sodium	ppm	ASTM D5185m		3	3	3
Potassium	ppm	ASTM D5185m	>20	9	11	21
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>4	0.2	0.4	0.4
Nitration	Abs/cm	*ASTM D7624	>20	4.8	7.8	7.9
Sulfation	Abs/.1mm	*ASTM D7415	>30	10.0	19.6	18.7
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	9.4	15.3	14.1
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	2.5	7.9	7.9



OIL ANALYSIS REPORT








VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROP	EHIIES	method	iiiiii/base	current	riistory i	nistoryz
Visc @ 100°C	cSt	ASTM D445	15.4	13.6	13.5	12.8

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number Test Package : FLEET

: GFL0072198 : 05918358 Unique Number : 10590272

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 08 Aug 2023 Diagnosed : 09 Aug 2023 Diagnostician : Jonathan Hester

GFL Environmental - 094 - Cedartown 2097 Buchanan Highway Cedartown, GA

US 30125 Contact: WILLIAM FOSTER william.foster@gflenv.com T: (800)207-6618

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: GFL094 [WUSCAR] 05918358 (Generated: 08/11/2023 14:00:59) Rev: 1