


# **OIL ANALYSIS REPORT**



# KEMP QUARRIES / RIVER VALLEY BACKBONE **WL088**

Component **Front Differential** 

**MOBIL MOBILTRANS HD 50 (--- GAL)** 





### DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor. ( Customer Sample Comment: Hour meter 6146)

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the oil.

#### **Fluid Condition**

The condition of the oil is acceptable for the time in service.


5 HD 50 ( GAL)  #2015 Nex2015 Jun2016 M#2017 Aug2018 Aug2019 M#2021 Jun2022 Aug201						
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0085866	PCA0070232	PCA0049259
Sample Date		Client Info		09 Aug 2023	14 Nov 2022	17 Feb 2022
Machine Age	hrs	Client Info		36443	5802	5321
Oil Age	hrs	Client Info		30641	5802	3907
Oil Changed		Client Info		Not Changd	Changed	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
WEAR META	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	26	91	51
Chromium	ppm	ASTM D5185m	>3	0	<1	<1
Nickel	ppm	ASTM D5185m	>3	0	0	<1
Titanium	ppm	ASTM D5185m	>2	<1	<1	<1
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>30	4	4	3
Lead	ppm	ASTM D5185m	>13	<1	<1	2
Copper	ppm	ASTM D5185m	>103	2	10	6
Tin	ppm	ASTM D5185m	>5	0	<1	<1
Antimony	ppm	ASTM D5185m	>5			<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	8	4
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		<1	<1	<1
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		12	8	12
Calcium	ppm	ASTM D5185m		2944	2882	3308
Phosphorus	ppm	ASTM D5185m		1032	1033	1194
Zinc	ppm	ASTM D5185m		1247	1262	1506
Sulfur	ppm	ASTM D5185m		4967	6008	5235
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>100	29	46	21
Sodium	ppm	ASTM D5185m		0	0	<1
Potassium	ppm	ASTM D5185m	>20	1	2	1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>.2	NEG	NEG	NEG
_ \^/ .		*) //		NEO	NIEO	NIEO

Free Water


scalar \*Visual



# **OIL ANALYSIS REPORT**









Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package : MOB 1

: PCA0085866 : 05924557 : 10604504

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Aug 2023 : 16 Aug 2023 Diagnosed Diagnostician : Sean Felton

Kemp Quarries - River Valley - Backbone

5600 S Hwy 253 Huntington, AR US 72940

Contact:

T:

F:

backbone@rivervalleyquarries.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)