


PROBLEM SUMMARY

Area [98331669] Machine Id KR-GR-001010 TRAVEL - DEMOLD MANIPLUX CRANE Component Gearbox

WEAR

Fluid GEAR OIL ISO 460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component if applicable. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Iron	ppm	ASTM D5185m	>200	A 343				
Debris	scalar	*Visual	NONE	🔺 MODER				

Sample Rating Trend

Customer Id: KRAKIR Sample No.: PCA0102557 Lab Number: 05924827 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDE	D ACTIONS			
Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component if applicable.
Resample			?	We recommend an early resample to monitor this condition.
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Area [98331669] Machine Id KR-GR-001010 TRAVEL - DEMOLD MANIPLUX CRANE Component

Gearbox

Fluid GEAR OIL ISO 460 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of particles present in this sample.

A Wear

Gear wear is indicated.

Contamination

Moderate concentration of visible dirt/debris present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		-		Aug2023		
SAMPLE INFOR		method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0102557		
Sample Date		Client Info		10 Aug 2023		
Machine Age	hrs	Client Info		0		
Dil Age	hrs	Client Info		0		
Dil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METAL	S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>200	4 343		
Chromium	ppm	ASTM D5185m	>15	2		
Nickel	ppm	ASTM D5185m	>15	<1		
Titanium	ppm	ASTM D5185m		1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	3		
_ead	ppm	ASTM D5185m	>100	<1		
Copper	ppm	ASTM D5185m	>200	<1		
Tin	ppm	ASTM D5185m	>25	0		
Vanadium	ppm	ASTM D5185m	- 10	0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	50	0		
Barium	ppm	ASTM D5185m	15	0		
Volybdenum	ppm	ASTM D5185m	15	<1		
Vanganese	ppm	ASTM D5185m		4		
Vagnesium	ppm	ASTM D5185m	50	9		
Calcium	ppm	ASTM D5185m	50	7		
Phosphorus	ppm	ASTM D5185m	350	263		
Zinc	ppm	ASTM D5185m	100	90		
Sulfur	ppm	ASTM D5185m	12500	222		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	16		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	43		
FLUID DEGRA		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.85	1.07		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	LIGHT		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE			
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Free Water	scalar	*Visual		NEG		
				<i>y.</i>		


Sample Rating Trend

WEAR

Contact/Location: WALLACE WARD - KRAKIR



OIL ANALYSIS REPORT



Contact/Location: WALLACE WARD - KRAKIR