

PROBLEM SUMMARY

Sample Rating Trend

VISUAL METAL

Wachine Id VOLVO VLN630 7950 (S/N 4V4MC9EG3N173867)

Transmission

PETRO CANADA TRAXON SYNTHETIC MTF 75W80 (--- GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATION	PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	NORMAL	NORMAL		
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	NONE		

Customer Id: PERBRIDE **Sample No.:** PCA0099149 Lab Number: 05931225 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

21 Nov 2022 Diag: Jonathan Hester





Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



12 May 2022 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



03 Nov 2021 Diag: Don Baldridge

DIRT



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. Elemental level of silicon (Si) above normal. The condition of the fluid is acceptable for the time in service.





OIL ANALYSIS REPORT

Sample Rating Trend

VISUAL METAL

VOLVO VLN630 7950 (S/N 4V4MC9EG3N173867)

Component

Transmission

PETRO CANADA TRAXON SYNTHETIC MTF 75W80 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

🔔 Wear

Moderate concentration of visible metal present. All component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid


Fluid Condition


The condition of the fluid is acceptable for the time in service.

F 75W80 (GAI	L)			احصوا		
CAMPLE INCOR	AATIONI	Aug2020	Junž021 Novž021	May2022 Nov2022	May2023	history.O
SAMPLE INFORM	/IATION		limit/base	current	history1	history2
Sample Number		Client Info		PCA0099149	PCA0081159	PCA0074373
Sample Date		Client Info		15 May 2023	21 Nov 2022	12 May 2022
Machine Age	mls	Client Info		683788	620432	599627
Oil Age	mls	Client Info		524577	0	599627
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	33	41	<1
Chromium	ppm	ASTM D5185m	>10	<1	<1	0
Nickel	ppm	ASTM D5185m		0	0	0
Titanium	ppm	ASTM D5185m		<1	<1	0
Silver	ppm	ASTM D5185m		0	0	1
Aluminum	ppm	ASTM D5185m	>50	5	4	<1
Lead	ppm	ASTM D5185m	>50	0	0	<1
Copper	ppm	ASTM D5185m	>200	18	27	<1
Tin	ppm	ASTM D5185m	>10	0	<1	<1
Antimony	ppm	ASTM D5185m				
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	0	0
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m		0	2	0
Manganese	ppm	ASTM D5185m		4	5	<1
Magnesium	ppm	ASTM D5185m	3	2	3	2
Calcium	ppm	ASTM D5185m	731	622	566	906
Phosphorus	ppm	ASTM D5185m	628	532	495	637
Zinc	ppm	ASTM D5185m	1	1	7	2
Sulfur	ppm	ASTM D5185m	2556	4652	5183	4638
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	39	55	3
Sodium	ppm	ASTM D5185m		2	2	0
Potassium	ppm	ASTM D5185m	>20	2	3	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG





OIL ANALYSIS REPORT






GRAPHS











Laboratory Sample No. Lab Number Unique Number : 10616496

: PCA0099149 : 05931225

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 22 Aug 2023 Diagnosed : 23 Aug 2023 Diagnostician : Don Baldridge

PERDUE FARMS - BRIDGEVILLE

8634 E NEWTON RD BRIDGEVILLE, DE US 19933

Contact: GEORGE LACATES

Test Package : FLEET Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: