


OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Machine Id
slider press Crowncork seal
 Component
Circulating System
 Fluid
PETRO CANADA PURITY FG WHITE OIL 15 (--- GAL)

DIAGNOSIS




Recommendation

Debris appears to be metal shavings and organic material similar to wax. Suspect build up is accumulation of metal particles from the manufacturing process combined with the oil protectant. Debris is highly magnetic and partially flammable.

SAMPLE INFORMATION



| | method | limit/base | current | history1 | history2 |
|---------------|-------------|-------------|--------------------|----------|----------|
| Sample Number | Client Info | | PCA05933046 | --- | --- |
| Sample Date | Client Info | | 22 Aug 2023 | --- | --- |
| Machine Age | hrs | Client Info | 0 | --- | --- |
| Oil Age | hrs | Client Info | 0 | --- | --- |
| Oil Changed | | Client Info | N/A | --- | --- |
| Sample Status | | | NORMAL | --- | --- |

SAMPLE IMAGES

| | method | limit/base | current | history1 | history2 |
|-----------|--------|------------|--|----------|----------|
| Color | | |  | no image | no image |
| Bottom | | |  | no image | no image |
| PrtFilter | | |  | no image | no image |

OIL ANALYSIS REPORT

GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA05933046 **Received** : 23 Aug 2023
Lab Number : **05933046** **Diagnosed** : 19 Sep 2023
Unique Number : 10618317 **Diagnostician** : Doug Bogart
Test Package : TEST (Additional Tests: FilterPatch, KF)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

YVETTE TRZCINSKI
 850 WESTBROOKE PKWY
 WAUKESHA, WI
 US 53186
 Contact: YVETTE TRZCINSKI
 yvette.trzcinski@hfsinclair.com

T:
F: